

## Technify Motors GmbH Platanenstrasse 14 09356 Sankt Egidien, Germany

Tel: +49 37204 696 0 Fax: +49 37204 696 2912 www.centurion-engines.com info@centurion-engines.com

SB TMG 125-1018 P1, Rev. 1

## **SERVICE BULLETIN**

## **PRIORITY 1 - SAFETY**

Service Bulletin No. /

SB TMG 125-1018 P1, Revision 1 / February 05, 2015

Date:

Subject: Start Monitoring Loom and Mapping

Type affected:

TAE 125-02-99 and TAE 125-02-114

Models affected:

All engines with Dual Mass Flywheel (DMF)

Classification:

Category P1 – SAFETY

Time of Compliance:

Measures have to be accomplished within the next 100 flight hours or with the next inspection, whichever occurs first.

Reason:

Cases of a broken gearbox drive shaft were reported to Technify Motors GmbH. Investigations showed a possible overload of the gearbox drive shaft during starting of the engine or during restarting of the engine inflight.

Correction:

- Installation of a start phase monitoring system in accordance with IM-02-02, Chapter 13.08.16, Issue 4, Revision 1 or later approved revisions.
- Installation of the latest Firmware / Software Mapping in accordance with TM TAE 000-0007 Revision 28 or later approved revisions.

Note:

Please observe applicable published aircraft service bulletins for further instructions:

- SB TMG 601-1007 P1, revision 3 or later approved revisions (for Cessna 172)
- SB TMG 651-1004 P1, revision 2 or later approved revisions (for Piper PA28)
- SB TMG 691-1002 P1, revision 2 or later approved revisions (for DA40 D with TAE 125-02-114 engine)
- MSB D4-097/2 or later approved revisions (for DAI DA40 D)
- MSB 42-109/1 or later approved revisions (for DAI DA42)
- SB 141201, revision 1 or later approved revisions (for DR400)

Checked	
B. Metzdorf, CVE  D. Hartung, Office of Airworthiness	



## Technify Motors GmbH Platanenstrasse 14 09356 Sankt Egidien, Germany

Tel: +49 37204 696 0 Fax: +49 37204 696 2912 www.centurion-engines.com info@centurion-engines.com

SB TMG 125-1018 P1, Rev. 1

■ CAUTION: Compliance with the Service Bulletins listed above is necessary! Compliance with previous revisions does not

constitute compliance with this SB.

Remarks: -

**Approval:** The technical information contained in this document has been approved

under the authority of EASA Design Organisation Approval No.

EASA.21J.010.