



Continental Aerospace  
Technologies GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 37204 696 0  
Fax: +49 37204 696 2912  
www.continentaldiesel.com  
support@continentaldiesel.com

SB CG 125-1026 P1

## SERVICE BULLETIN

### PRIORITY 1 – SAFETY

**Service Bulletin No. / Date:** SB CG 125-1026 P1, Initial Issue / October 23, 2020

**Subject:** Replacement of the Timing Chain

**Type affected:** TAE 125-02-114 (Version 01 engine)

**Models affected:** All

**Classification:** Category P1 – SAFETY

**Time of Compliance:** Engines up to 600 flight hours:  
Measures have to be accomplished with the next 600 hours maintenance action.



Engines between 600 flight hours and 900 flight hours  
Measures have to be accomplished within the next 25 flight hours or with the next maintenance action, if not already carried out.

**Reason:** Cases of a fracture of the timing chain before the end of its life time were reported to Continental Aerospace Technologies GmbH.

**Correction:** Reduction of the replacement interval of the timing chain from 900 h to 600 h.  
Replace the timing chain in accordance with RM-02-02, Chapter 72-30.02, Issue 5, Revision 0 or later approved revisions.

**Remarks:** -

**Approval:** The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval No. EASA.21J.010.

Checked T. Franke, CVE 	Approved  23. Oct. 2020 D. Hartung, Office of Airworthiness
---	--

Replaces Service Bulletin No. / Date: -

Page 1 / 1