



Technify Motors GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 37204 696 0
Fax: +49 37204 696 2912
www.centurion-engines.com
info@centurion-engines.com

SL TMG 000-1007, Initial Issue

Service Letter

Service Bulletin No. SL TMG 000-1007, Initial Issue
Date: April 9, 2018

Subject: Temporary power loss due to water contamination

Type affected: all

Models affected: all

Classification: Category SL – SERVICE LETTER



Time of Compliance: -

Reason: Several temporary power losses of 3-6 seconds duration were reported to TMG. The majority shortly after take-off. Although the investigation is still ongoing, the most likely root cause is water contamination of the fuel.

Correction: Make sure that the fuel is sufficiently drained prior to the flight and that the fuel is drained at all draining points.
Refer to the applicable AFM / POH for the correct draining procedure.

Remarks: -

Approval: The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval No. EASA.21J.010.

Checked  A. Wille, CVE	Approved  D. Hartung, Office of Airworthiness
--	--

Replaces Service Bulletin No. / Date:
-