



Continental Aerospace Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 37204 696 0
Fax: +49 37204 696 2912
www.continentaldiesel.com
support@continentaldiesel.com

SL TMG 125-1005, Revision 1

Service Letter

Service Bulletin No. SL TMG 125-1005, Revision 1
Date: January 30, 2020

Subject: Temporary power loss

Type affected: TAE 125-02-99 and TAE 125-02-114

Models affected: all

Classification: Category SL – SERVICE LETTER

Time of Compliance: -



Reason: Several temporary power losses of 3-6 seconds duration were reported to Continental Aerospace Technologies GmbH. The majority shortly after take-off. Although the investigation is still ongoing, the most likely root cause is a temporarily jammed exhaust valve.

Correction: If a temporary power loss has occurred:

1. Contact Continental Aerospace Technologies GmbH prior to the next flight.
2. Download the FADEC data and send it to support@continentaldiesel.com for a detailed analysis and further instruction.

Remarks: -

Approval: The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval No. EASA.21J.010.

Checked A. Wille, CVE 	Approved D. Hartung, Office of Airworthiness 
---	---

Replaces Service Bulletin No. / Date:
SL TMG 125-1005, Initial Issue / October 19, 2018

Page 1 / 1