



## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:**  
**Service Bulletin No. / Date**

TM TAE 000-0003, Revision 68 / 15.06.2017  
TM TAE 000-0003, Revision 68 / June 15, 2017

**Betrifft:**  
**Subject:**

Autorisierte Wartungsbetriebe  
*authorized maintenance organisations*

**Betroffenes Luftfahrtgerät:**  
**Type affected:**

alle Technify Motors GmbH Produkte  
*all Technify Motors GmbH products*

**Betroffene Geräte-Nr.:**  
**Models affected:**

alle  
*all*

**Einstufung:**  
**Compliance:**

Kategorie 5 – nur zur Information  
*Category 5 – for information only*

**Dringlichkeit:**  
**Accomplishment:**

sofort  
*immediately*

**Grund:**

Wartungsarbeiten dürfen nur von Personen durchgeführt werden, die durch die zuständige Luftfahrtbehörde zur Durchführung dieser Arbeiten berechtigt wurden.

**Reason:**

*Maintenance work should only be performed by persons authorized through the competent authority of the respective country.*

**Maßnahmen:**

Personen sind durch die zuständige nationale Luftfahrtbehörde des jeweiligen Landes berechtigt oder zertifiziert Wartungsarbeiten durchzuführen. Um einen hohen Qualitätsstandard für unser Produkt zu gewährleisten empfiehlt Technify Motors GmbH den Betreibern dringend, bei der Durchführung von Wartungsarbeiten, nur die Service-Center zu nutzen, welche in diesem Service Bulletin aufgeführt sind.

**Correction:**

*Persons are authorized or certificated to perform maintenance by the competent national authority of the respective country. In order to ensure a high quality standard for our product, Technify Motors GmbH strongly recommends that operators only utilize the service-center described in this service bulletin when performing maintenance.*

**Hinweise:**

Die durch die zuständige Behörde erteilte Genehmigung als Instandhaltungsbetrieb, bleibt durch die Empfehlung der Technify Motors GmbH unberührt und wird insbesondere nicht automatisch erweitert.

Technify Motors GmbH empfiehlt folgende Instandhaltungsbetriebe:

**Remarks:**

*The approval granted by the competent authority as a maintenance organization remains unaffected by the recommendation of Technify Motors GmbH and is not extended automatically.*

*Technify Motors GmbH recommends the following maintenance organizations:*



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Armenia

|                  |  |
|------------------|--|
| Aremenia Airways | Ave. Azatutyan Bld. 12/1<br>Office 18<br>0014 Yerevan<br>ARMENIA |
|------------------|--|

### Australia

|  |  |
|--|--|
| Aircraft Engineers Associates PTY LTD              | Hangar 2, Beatty Road<br>Archerfield Airport 4108<br>AUD-Queensland<br>AUSTRALIA                                   |
| Aircraft Maintenance Specialists                   | 16 Pathfinder Drive<br>Aerodrome<br>4551 Caloundra, Queensland<br>AUSTRALIA  |
| CGG Aviation (Australia) Pty Ltd.                  | Hanger 106<br>10 Compass Road<br>6164 Jandakot Airport, WA<br>AUSTRALIA  |
| Phoenix Aviation                                   | 4 Murphy Court,<br>Darwin International Airport<br>PO Box 41119<br>0811 Casuarina Northern Territory,<br>AUSTRALIA |
| Riverina Air Motive PTY LTD                        | Hangar 58, Anderson Drive<br>5106 Parafield Airport, SA<br>AUSTRALIA   |
| Sport Air Services<br>c/o Australian Wings Academy | 19 Lores Bonney Circuit<br>4225 Bilinga Gold Coast Airport<br>AUSTRALIA  |



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Austria

|  |  |
|--|--|
| AAC Austrian Aircraft Corp.<br>Oest. LFZ GmbH    | Flughafen Linz<br>4063 Hoersching, AUSTRIA                           |
| AAC Austrian Aircraft Corp.<br>Oest. LFZ GmbH    | Flughafen Graz<br>8073 Feldkirchen, AUSTRIA                          |
| Aerotechnik GmbH Salzburg                        | Kröbenfeldstr. 12d<br>5020 Salzburg, AUSTRIA                         |
| Diamond Aircraft Industries GmbH                 | N.A. Ottostrasse 5<br>2700 Wiener Neustadt, AUSTRIA                  |
| Flugsportzentrum Tirol                           | Sonnenstr. 12A<br>6020 Innsbruck, AUSTRIA                            |
| HB-Flugtechnik GmbH                              | Dr. A. Schärfstr. 42<br>4053 Haid, AUSTRIA                           |
| Luftfahrzeug Wartungsbetrieb Krems<br>GmbH       | Flughafenstraße 19<br>3500 Krems, AUSTRIA                            |
| Luftfahrzeugtechnik Zell am See<br>GmbH & Co. KG | Kaprunerstrasse 15<br>5700 Zell am See, AUSTRIA                      |
| Urbe Aero GmbH                                   | Ferdinand Graf v. Zeppelinstraße 11<br>2700 Wiener Neustadt, AUSTRIA |

### Azerbaijan

|                            |  |
|----------------------------|--|
| SW Helicopter Services LLC | Zabrat-2 settlement<br>Airport<br>Baku, AZ1104, AZERBAIJAN |
|----------------------------|--|

### Bangladesh

|                   |  |
|-------------------|--|
| TAC Aviation Ltd. | Osmani International Airport<br>Sylhet, BANGLADESH |
|-------------------|--|



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Belgium

|                       |  |
|-----------------------|--|
| Abelag                | Luchthavenlei 1<br>Bus 66<br>2100 Antwerpen, BELGIUM                 |
| Aero Maintenance      | Chaussee de Nivelles 167<br>7181 Arquennes, BELGIUM                  |
| BVBA Gill Aviation    | Vliegied 60<br>8560 Wevelgem, BELGIUM                                |
| Styl Aviation         | PB 34 - Loods 5<br>Airport Antwerp<br>2100 Deurne / Antwerp, BELGIUM |
| Winters Aviation bvba | Leuchthavenlei 1 Bus 48<br>2100 Deurne, BELGIUM                      |

### Belize

|                    |   |
|--------------------|---|
| Tropic Air Limited | Coconut Drive<br>San Pedro Town, BELIZE |
|--------------------|---|

### Bermuda

|   |   |
|---|---|
| Longtail Aviation International Limited | 6 Southside Road<br>DD03 St. Georges<br>BERMUDA |
|---|---|

### Botswana

|                                      |                                   |
|--------------------------------------|-----------------------------------|
| Northern Air Maintenance (Pty.) Ltd. | Private Bag 159<br>Maun, BOTSWANA |
|--------------------------------------|-----------------------------------|



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                          | Adress  |
|-------------------------------|---|
| <b>Bulgaria</b>               |   |
| Air Scorpio Ltd.              | 73 Persenk Str.<br>1164 Sofia, BULGARIA                   |
| Bluewind Aviation Ltd.        | 1 Brussels bul,<br>building no. 5<br>1540 Sofia, BULGARIA |
| Bulgarian Aeronautical Center | Sofia Airport<br>1540 Sofia, BULGARIA                     |
| DEDALUS Aviation Services     | LESNOVO Airport<br>2119 Sofia, BULGARIA                   |

|                                   |  |
|-----------------------------------|--|
| <b>Canada</b>                     |  |
| Air Quasar Ltd.                   | 6050 Route de l'aéroport<br>J3Y 8Y9 St. Hubert, Quebec<br>CANADA                           |
| Altair Aviation Ltd.              | #130 11465 Baynes Road<br>V3Y 2B4 Pitt Meadows, British Columbia<br>CANADA                 |
| Avworks Aerospace                 | A3-349 Noorduyn Park<br>CALGARY AB T32-357<br>CANADA                                       |
| Diamond Aircraft Industries Inc.  | 1560 Crumlin Sideroad<br>N5V 1S2 London, Ontario<br>CANADA                                 |
| Fiskus Aircraft Inc.              | 42206 Airport Road<br>V2P 1A5 Chilliwack, British Columbia<br>CANADA                       |
| GDirect Aviation Maintenance Inc. | 220A 18799 Airport way<br>V3Y 2B4 Pitt Meadows, British Columbia<br>CANADA                 |
| Halcyon Aviation                  | #3 – 4340 King Street<br>Boundary Bay Airport<br>V4K 5B3 Delta, British Columbia<br>CANADA |
| Harvey Aviation Services Inc.     | 100 Rue #1,<br>GOV 1L0 St-Honoré, Quebec<br>CANADA   |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
5/37



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                                | Adress   |
|-------------------------------------|--|
| Klarenbach Aviation Ltd.            | Unit E1, 333 Noorduyn Park<br>T3Z 3S7 Calgary, Alberta<br>CANADA                               |
| Nason Aviation Inc.                 | 12375 – 132 Street<br>T5L 1P9 Edmonton, Alberta<br>CANADA                                      |
| M.B. Aero Inc.                      | 706 South Gate Rd.<br>R1A 3P8 St. Andrews, Manitoba<br>CANADA                                  |
| Safari Express Aircraft Maint. Ltd. | Boundary Bay Airport<br>Unit 2 – 4340 King Street<br>V4K 0A5 Delta, British Columbia<br>CANADA |
| Sander Geophysics Ltd.              | 260 Hunt Club Road<br>K1V 1C1 Ottawa, Ontario<br>CANADA  |
| Saskatoon Ltd.                      | 28 Airport Crescent,<br>S7L 6G9 Saskatoon, Saskatchewan<br>CANADA                              |
| Xu Aviation Ltd.                    | 2537 Huron St.<br>N5V 5J1 London, Ontario<br>CANADA  |

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name  | Adress  |
|---|---|
| <b>China</b>  |   |
| AeroHawk Aircraft Engineering Co. Ltd.                    | Dagao Airport<br>Zhanhua County, Binzhou<br>256800 Shangdong<br>CHINA                   |
| Anhui Sky Aviation<br>International Flight Academy        | FeiXi district<br>SenLin Avenue, No. 3 WenDa Group<br>231201 HeFei, AnHui<br>CHINA      |
| AVIC Flight Academy                                       | 38# Airport Road<br>Changzhou District, Guangxi Province<br>543002 Wuzhou City<br>CHINA |
| Bei Da Huang General Aviation Co.                         | No480-8 Songhua Street<br>154004 Jiamusi City, Heilongjiang Province<br>CHINA           |
| Beijing XiangYu General Aviation Co. Ltd.                 | No. 324 West Palace Street,<br>065201 Yanjiao Town, Sanhe City, Hebei Province<br>CHINA |
| Chengdu Hot Aviation Technology Co., Ltd                  | No. 1186, Baicao Road, Hi-Tech West Zone,<br>611731 ChengDu, Sichuan<br>CHINA           |
| China Flying Dragon General Aviation Co.<br>Ltd.          | No. 16 Nanhai Street<br>Pingfang District, Harbin<br>Hei Long Jiang<br>CHINA            |
| Civil Aviation University of China                        | No. 2892, JinBei Road<br>Dongli District<br>300300 TianJin City<br>CHINA                |
| Hainan Aciation Academy Co. Ltd.                          | Three Gorges Airport<br>443007 City of Yichang, Hubei Province<br>CHINA                 |
| Hubei Sky-Blue International Aviation<br>Academy Co. Ltd. | 24F Building A<br>Optical Valley International<br>Wuhan<br>CHINA                        |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
7/37

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name  | Adress   |
|---|--|
| JinSheng General Aviation                                 | Lao Dong South Rd, Northwest<br>Aviation Building, 8 Layers, No 296<br>Xian City, Shaanxi Province, SN 29<br>CHINA |
| Liaoning Ruixiang General Aviation Co., Ltd.              | Caihu Airfield,<br>Faku County<br>110403 Shenyang, Liaoning Province<br>CHINA                                      |
| Ordos General Aviation Co, Ltd.                           | Yijin Huoluo Banner Airport<br>017200 Ordos City, Inner Mongolia,<br>CHINA   |
| Qingdao Jiutian International Flight<br>Academy Co., Ltd. | 6#, No 702 Shanhe Road, Chengyang District<br>266108 Qingdao, Shandong<br>CHINA                                    |
| Reetek United Aircraft<br>Engineering Co., Ltd.           | Room Dool, 5th Floor, Bldg. A<br>Tianqu Business Hotel<br>100621 Beijing<br>CHINA                                  |
| Shaanxi Phoenix International Flying<br>College Co Ltd.   | Liupanshan Airport<br>Guyuan, Ningxia<br>CHINA   |
| Shandong Bin Ao Aircraft<br>Industries Co., Ltd.          | Binzhou Dagao Hi-Tech Dev. Zone<br>Zhanhua County, Binzhou<br>256 800 Shandong Province<br>CHINA                   |
| Xin Jiang Tian Xiang Aviation College                     | Three North Road No. 110,<br>Bo Hua Hotel<br>Shi He Zi, Xin Jiang<br>CHINA   |
| Zhiyuan General Aviation Co., Ltd                         | No.1 Airport Road<br>Handan Airport, Handan City<br>056006 Hebei Province<br>CHINA                                 |

### Colombia

|            |   |
|------------|---|
| Tresa Itda | Aeropuerto Guaymaral Int. 1<br>Bogota, COLOMBIA |
|------------|---|

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
8/37





**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Cook Islands

|                    |  |
|--------------------|--|
| Air Rarotonga Ltd. | Rarotonga International Airport<br>Rarotonga, COOK ISLANDS |
|--------------------|--|

### Croatia

|                                 |  |
|---------------------------------|--|
| Diamond Aircraft Croatia d.o.o. | M.P. Miskine 72<br>42000 Varazdin, CROATIA |
|---------------------------------|--|

### Cyprus

|                            |  |
|----------------------------|--|
| Pegasus Flight Center Ltd. | Larnaca International Airport<br>Larnacy, CYPRUS |
|----------------------------|--|

### Czech Republic

|  |   |
|--|---|
| Aeroklub Ceske Republiky<br>Aeroclub of the Czech Republic | U Mlýna 3<br>14100 Praha 4-Sporilov<br>CZECH REPUBLIC     |
| Air Jihlava – Service s.r.o.                               | Hencov 61<br>586 01 Jihlava<br>CZECH REPUBLIC             |
| EEA Tech spol. s.r.o.                                      | Stare Mesto 310<br>56932 Stare Mesto<br>CZECH REPUBLIC    |
| OK AVIATION Services s.r.o.                                | Drásov 201<br>26101 Příbram<br>CZECH REPUBLIC             |
| TomiAIR s.r.o.   | Skuteckeho str. 1086/5<br>16300 Praha 6<br>CZECH REPUBLIC |



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Denmark

|                               |  |
|-------------------------------|--|
| Air Alpha Maintenance A/S     | Odense Airport<br>P.O. Box 630<br>5270 Odense N., DENMARK                          |
| Air Service International A/S | Stratusvej 1<br>7190 Billund, DENMARK  |
| Airservice Vamdrup AP         | Lufthavnsvej 7A<br>6580 Vamdrup, DENMARK   |
| North Flying A/S              | Lufthavnsvej 100<br>Aalborg Airport<br>9400 Norresundby, DENMARK                   |
| UNI-FLY A/S                   | Hans Christian Andersen Airport<br>Lufthavnvej 131, HG37<br>5270 Odense N, DENMARK |

### Ecuador

|                                       |  |
|---------------------------------------|--|
| ARICA<br>Aeroservicios Generales C.A. | Av. De las Américas, Aeropuerto<br>Simon Bolivar, Hangar 7<br>Guayaquil, ECUADOR |
|---------------------------------------|--|

### Egypt

|                           |   |
|---------------------------|---|
| Egyptian Aviation Academy | Imbaba Aerodrome<br>Giza Governorate, EGYPT |
|---------------------------|---|

### Finland

|   |  |
|---|--|
| Airfix Aviation Oy                                | Tullimiehentie 4-6<br>01530 Vantaa, FINLAND  |
| Arctic AirService Ky                              | Lentopaikantie 1<br>97700 Ranua, FINLAND     |
| Joen Service Oy                                   | Lentoasemantie 30<br>80140, Joensuu, FINLAND |
| Konekorhonen Oy                                   | Ilmailutie 74<br>05820 Hyvinkää, FINLAND     |
| Lapland Technical College<br>Aircraft Maintenance | Kairatie 75<br>96190 Rovaniemi, FINLAND      |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**10/37**



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name  | Adress  |
|---|---|
| <b>France</b>   |   |
| Aéraudit  | Aérodrome Toulouse-Lasbordes<br>40, rue René Lagasse<br>31130 Balma, FRANCE                             |
| Aéro Carpiquet Sarl                                       | Le Haut Marcelet<br>14740 Saint Manvieu Norrey, FRANCE  |
| Aéro Club Air France Nord                                 | Aérodrome du Plessis-Belleville<br>60950 Ermenoville, FRANCE  |
| Aéro Dordogne Services                                    | Aéroport de Bergerac<br>24100 Bergerac, FRANCE  |
| Aéro Flandre Maintenance                                  | Z.I. du petit pacault Aérodrome<br>59660 Merville, FRANCE   |
| Aéro Services   | Aérodrome<br>2492 Route de Thiberville<br>27306 Bernay, FRANCE  |
| Aéro Services Mimizan                                     | Aérodrome<br>40200 Mimizan, FRANCE  |
| Aéroclub d'Orléans et du Loiret (ACOL)                    | Aérodrome d'Orléans<br>45550 St. Dennis de l'Hotel, FRANCE  |
| Aéroclub de Bordeaux                                      | Aérodrome de Léognan-Saucats<br>305 Avenue de Mont de Marsan<br>33850 Leognan, FRANCE                   |
| Aeroclub de Champagne                                     | Aerodrome de Reims-Prunay<br>51360 Prunay, FRANCE   |
| Aéro-Club de L'Herault                                    | Languedoc - Roussillon<br>Aéroport International de<br>Montpellier Méditerranée<br>34134 Maugio, FRANCE |
| Aéroclub de la Haute-Saone /<br>AC du Pays de Montbeliard | Aérodrome de Vesoul-Frotey<br>BP 60229<br>70004 Vesoul Cedex, FRANCE                                    |
| Aeroclub du Dauphine<br>Maintenance                       | Aerodrome<br>38420 Le Versoud, FRANCE   |
| Aéroclub du Havre Jean Maridor                            | Aérodrome du Havre-Octéville<br>76620 Le Havre, FRANCE  |
| Aéroclub Paul Tissandier                                  | Aérodrome de St. Cyr<br>78210 St. Cyr l'Ecole, FRANCE   |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
11/37



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                              | Adress   |
|-----------------------------------|--|
| Aeroglide                         | Sainte Anne<br>04700 Puimichel, FRANCE   |
| Aeronav87 Maintenance             | Aéroport International<br>87100 Limoges, FRANCE                                    |
| AEROZING SARL                     | Aérodrome d'Aix Les Milles<br>Chemin de la Badesse<br>13290 Aix-les-Milles, FRANCE |
| Air et Compagnie Maintenance      | Aéroport de Toussus le Noble Bat.313<br>78117 Toussus le Noble, FRANCE             |
| Air Intervention Sarl             | Aérodrome RN 10<br>37250 Sorigny, FRANCE   |
| Air Maintenance                   | Aéroport du Touquet<br>62520 Le Touquet, FRANCE                                    |
| Air Services Caraibes S.A.R.L.    | Aéroport du Raizet<br>97139 Abymes<br>Guadeloupe, French West Indies<br>(FRANCE)   |
| Airways Formation                 | Aérodrome Agen La Garenne<br>47520 Le Passage, FRANCE                              |
| Alsace Air Maintenance            | Aérosport de Colmar<br>68000 Colmar, FRANCE  |
| ATA                               | Aerogare D'Avignon<br>141, Allee de la Chartreuse<br>84140 Montfavet, FRANCE       |
| Avialaval sarl                    | Aérodrome Laval Entrammes<br>53260 Entrammes, FRANCE                               |
| Belledonne Aéro Maintenance       | Aérodrome du Versoud<br>38420 Le Versoud, FRANCE                                   |
| Blue Aéro SARL                    | Aéroport de Grenoble St Geoirs<br>38590 St Etienne de St Geoirs, FRANCE            |
| Bourgogne Aéro Services           | Hangar Nord<br>Aérodrome Auxerre Branches<br>89380 Appoigny, FRANCE                |
| C.E.A.P.R. SAS                    | 1 Route de Troyes<br>21121 Darois, FRANCE  |
| Centre de Pilotage Choletais Sarl | Aérodrome le Pontreau<br>49300 Cholet, FRANCE                                      |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page  
12/37**



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                          | Adress   |
|-------------------------------|--|
| Dinan Aviation SIBA Avionique | Aérodrome de Dinan Trelivan<br>22100 Dinan, FRANCE   |
| Egide Aviation                | Aéroport Chateauroux Deols<br>Rue Georges Clemenceau Bat. 1250<br>36130 Deols, FRANCE          |
| EPAG                          | Atelier d'entretien avions<br>agrément JAR 145 - F266<br>F-59660 Aérodrome de Merville, FRANCE |
| ESMA                          | Aéroport Montpellier Méditerranée<br>CS 1000534137 Manguio Cedex, FRANCE                       |
| Fly West Loisirs Sarl         | 12 Allée Raymond Bazin<br>Aérodrome<br>85200 Fontenay le Comté, FRANCE                         |
| France Aviation               | Aéroport Toussus- Le Noble<br>F-78117 Toussus- Le Noble, FRANCE                                |
| Icarius Aerotechnics          | Aéropole<br>05130 Tallard, FRANCE  |
| Jolliet Electronique          | Rue du Pommier<br>39100 Gevry, FRANCE  |
| Lille Aéro Maintenance SARL   | Aéroport de Lille Lesquin<br>Espace Aviation Loisirs<br>59810 Lesquin, FRANCE                  |
| Locavia                       | Aérodrome de Lille-Marcq<br>59587 Bondues, FRANCE  |
| Marre Aviation                | Aérodrome<br>26200 Montelimar, FRANCE  |
| Nogaro Aviation               | Aerodrome<br>32110 Nogaro, FRANCE  |
| PAM                           | Hangar H5<br>Airport Lyon / Bron<br>69500 Bron, FRANCE   |
| Paris Nord Technique          | Aérodrome de Persan-Beaumont<br>95340 Bernes sur Oise, FRANCE                                  |
| Pitet Air Service             | Route de l'Aviation<br>88000 Dogneville, FRANCE  |
| Rectimo Aviation s.a.s.       | Aéroport Chambéry / Aix les Bains<br>73420 Viviers du Lac, FRANCE                              |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page  
13/37**

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                          | Adress   |
|-------------------------------|--|
| Riviera Plane Maintenance RPM | 54, Aéroport de Cannes<br>Mandelieu, Hangar 7<br>06150 Cannes La Bocca, FRANCE       |
| Roanne Aéro Maintenance       | Aéroport de Roanne Renaison<br>Route de Combray<br>42155 St Léger Sur Roanne, FRANCE |
| Robin Aircraft                | 1 Route de Troyes<br>21121 Darois, FRANCE  |
| SEFA                          | Rue de l'Aviation<br>BP 30080<br>31603 Muret, FRANCE                                 |
| Seram – Aeromat               | Aérodrome de Villefranche<br>69620 Frontenas, FRANCE                                 |
| Xenon Aviation                | Aerodrome de Vannes<br>56250 Monterblanc, FRANCE                                     |

### Germany

|  |   |
|--|---|
| Aero Club Coburg e.V.                            | Brandensteinsebene<br>96450 Coburg, GERMANY                             |
| Aero Technik Klaus Siemers GmbH                  | Flughafen Geb. 347<br>Geschäftsfliegerzentrum<br>22335 Hamburg, GERMANY |
| Aerodata AG                                      | Hermann-Blenk-Str. 34-36<br>38108 Braunschweig, GERMANY                 |
| Aero-Service-Donauwörth<br>Luftfahrttechnik GmbH | Flugplatz<br>86682 Genderkingen-Forstmahd, GERMANY                      |
| Aerowest GmbH                                    | Nordstraße 18<br>30669 Hannover, GERMANY                                |
| Air Service Fiedler                              | Wilhermsdorfer Straße 33<br>09387 Jahnsdorf, GERMANY                    |
| Air Service Klausheide GmbH                      | Airportallee 1<br>48268 Greven, GERMANY                                 |
| Aircraft-Service Luftfahrttechnik                | Flugplatz Mainz Finthen<br>Halle 5a<br>55126 Mainz, GERMANY             |
| AirPlus Maintenance GmbH                         | Flughafen 28<br>88046 Friedrichshafen, GERMANY                          |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
14/37

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name  | Adress  |
|---|---|
| ARDEX Aviation Maintenance GmbH                           | Flugplatz 4<br>16866 Kyritz, GERMANY  |
| Augsburg Air Service GmbH                                 | Flughafenstraße 5<br>86169 Augsburg, GERMANY                                  |
| Cirrus Deutschland Maintenance                            | Flugplatz A1<br>14959 Schönhagen, GERMANY                                     |
| Diamond Aircraft Industries<br>Deutschland GmbH           | Hans-Fleissner-Str.<br>63329 Egelsbach, GERMANY                               |
| DOTEC GmbH  | Am Flughafen 26<br>87766 Memmingerberg, GERMANY                               |
| Flugausbildungsverein<br>Erdmannhausen e.V.               | Kirchbergerstr. 3<br>71729 Erdmannhausen, GERMANY                             |
| Flugtechnik Stuttgart GmbH                                | General Aviation Terminal (GAT)<br>70629 Stuttgart Flughafen, GERMANY         |
| Flugzeugreparatur Damme GmbH                              | Am Flugplatz 20<br>49401 Damme, GERMANY                                       |
| Flugzeugservice Petersen                                  | Ochsenweg 203<br>24941 Flensburg, Germany                                     |
| Flugzeugwerft Möller GmbH                                 | Flugplatz Hangelar<br>53757 Sankt Augustin, GERMANY                           |
| FSB Aircraft Maintenance GmbH                             | Flugplatz B2<br>14959 Schönhagen, GERMANY                                     |
| FSG Flugservice GmbH                                      | Flugplatz<br>61203 Reichelsheim, GERMANY                                      |
| Gilbert Luftfahrttechnik GmbH & Co KG                     | City Airport Mannheim<br>Seckenheimer Landstr. 170<br>68163 Mannheim, GERMANY |
| Gomolzig Flugzeug- und Maschinenbau<br>GmbH               | Eisenwerkstr. 9<br>58332 Schwelm, GERMANY                                     |
| Gomolzig Flugzeugwerft Siegerland                         | Flugplatz Siegerland EDGS<br>Werftstraße 1<br>57299 Burbach, GERMANY          |
| H.B. Sportflugzeug-Service GmbH                           | Brunshofstr. 5<br>45470 Mühlheim, GERMANY                                     |
| Hanseatischer Fliegerclub Frankfurt e.V., NL<br>Egelsbach | Flugplatz, Haus 4a<br>63329 Egelsbach, GERMANY                                |
| Helitec Helicopter Technik GmbH                           | Flughafen<br>34379 Calden, GERMANY  |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**15/37**



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                                     | Adress  |
|--|---|
| Helitec Helicopter Technik GmbH          | Flughafen 13<br>06188 Oppin, GERMANY                                      |
| K. Malter Air Service                    | Am Birkenbrühl / Flugplatz<br>91074 Herzogenaurach, GERMANY               |
| LTB Sammet GmbH                          | Flugplatz Heubach<br>73540 Heubach, GERMANY                               |
| Luftfahrt-Service Haiml GmbH             | Freiburger Straße 15b<br>79427 Eschbach Flugplatz, GERMANY                |
| MR Flugtechnik GmbH                      | Am Flugplatz 19<br>31137 Hildesheim, GERMANY                              |
| Piloten-Service Robert Rieger GmbH       | Flugplatz 2<br>94474 Vilshofen, GERMANY                                   |
| Piper + Jet Maintenance AG               | Fieseler-Storch-Straße 10<br>34379 Calden, GERMANY                        |
| Porta Air Service GmbH & Co KG           | Flughafen 9<br>32457 Porta Westfalica, GERMANY                            |
| Röder Präzision GmbH                     | Flugplatz Egelsbach<br>63329 Egelsbach, GERMANY                           |
| Scheiling Aircraft Service               | Zum Tower 10<br>01917 Kamenz, GERMANY                                     |
| Solomo Flugzeugservice GmbH              | Flugplatz<br>Zeppelinstr 1<br>19370 Parchim, GERMANY                      |
| Solution Air GmbH                        | Berliner Allee 11-21<br>Geb. 360, Flughafen<br>66482 Zweibrücken, GERMANY |
| Spessart Air Service GmbH                | Am Flugplatz<br>63762 Großostheim, GERMANY                                |
| Westflug Aachen Luftfahrt GmbH & Co. KG  | Flugplatz Merzbrück<br>52146 Würselen, GERMANY                            |
| Wilhelm Tank GmbH & Co.<br>Mariensiel KG | Flugplatz Mariensiel<br>26452 Sande, GERMANY                              |





**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Greece

|                                  |  |
|----------------------------------|--|
| Aeroservices S.A.                | 3 Thermopylon Street<br>15233 Chalandri, GREECE  |
| Airflytech Ike                   | Heraklion "Nikos Kazantzakis"<br>International Airport<br>71601 Nea Alikarnassos, GREECE |
| DEDALUS Aviation Services        | Thessaloniki International Airport "Makedonia"<br>55103 Thessaloniki, GREECE             |
| Egnatia Aviation Ltd.            | Kavala International Airport<br>64200 Chrysoupoli-Kavala, GREECE                         |
| Greek Air Aviation Services Ltd. | 81, Archimidous str.<br>19400 Koropi – Attica, GREECE                                    |

### Hungary

|  |  |
|--|--|
| Avicraft Ltd.                                  | Bercsenyi u. 45<br>2700 Cegled, HUNGARY  |
| Hungarian Aircraft Technology and Service Ltd. | International Airport<br>Fertöszentmiklos, PO Box 23<br>9444 Fertöszentmiklos, HUNGARY |
| Magyar Repülökadémia KFT                       | Kazinczy Utca 18<br>7143 Öcsény, HUNGARY   |
| Pannon Air Service KFT                         | Tököl Airport<br>Repülöter Pf. 32<br>2316 Tököl, HUNGARY                               |

### India

|   |   |
|---|---|
| Asia Pacific Flight Training Academy Ltd. | GMR HIAL Airport Office<br>Rajiv Gandhi International Airport<br>Shamshabad, Hyderabad-50040<br>Andhra Pradesh, INDIA |
| Chimes Aviation Private Ltd.              | 61, Sector 44, Gurgaon<br>122003 Haryana, INDIA   |



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Indonesia

|                            |  |
|----------------------------|--|
| PT ASI Pudiastuti Aviation | Country Woods TH14<br>12120 Jakarta, INDONESIA |
|----------------------------|--|

### Italy

|                                    |  |
|------------------------------------|--|
| Aero Club Vercelli                 | Viale Aeronautica, 46<br>13100 Vercelli, ITALY             |
| ATS s.r.l.                         | Via dell'Aeroporto, 44/A<br>43100 Parma Airport, ITALY     |
| Diamond Aero s.r.l.                | Aeroporto Roma Urbe<br>Via Salaria 825<br>00138 Rom, ITALY |
| Flying Club Sabaudia               | Via Litoranea<br>Podere 2082<br>04016 Sabaudia, ITALY      |
| Glasfaser Italiana s.p.a.          | Via delle Ghiaie, 3<br>24030 Valbrembo, BG, ITALY          |
| Max Aviation s.r.l.                | Strada Castiglione<br>01100 Viterbo, ITALY                 |
| Officine Aeronautiche Ghidotti Srl | Via dei Grilli 5<br>41012 Carpi, ITALY                     |
| Professione Volare s.r.l.          | Via C. Seganti, 103<br>47121 Forli (FC), ITALY             |
| Turin Flying Institute s.r.l.      | Strada San Maurizio, 12<br>10072 Caselle Torinese, ITALY   |

### Ireland

|   |  |
|---|--|
| Aircraft Technical Support Ireland Ltd. | Weston Airport<br>Leixlip, Co Kildare, IRELAND |
| Shamrock Aviation Services Ltd.         | Waterford Airport<br>Waterford, IRELAND        |



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Japan

|                          |   |
|--------------------------|---|
| Alpha Aviation Co., Ltd. | 5-21 Mita 3-chome<br>108-0073 Minato-ku, Tokyo<br>JAPAN |
| IBEX AVIATION Co., Ltd.  | 5-21-12 Osawa<br>Mitaka-city<br>181-0015 Tokyo<br>JAPAN |

### Jordan

|                       |                                      |
|-----------------------|--------------------------------------|
| Ayla Aviation Academy | P.O. Box 2434<br>77100 Aqaba, JORDAN |
|-----------------------|--------------------------------------|

### Kenya

|                             |   |
|-----------------------------|---|
| Aeronav Maintenance Ltd.    | Wilson Airport<br>P.O. Box 74714<br>00200 Nairobi<br>KENYA    |
| Hawk Aviation Services Ltd. | P.O. Box 43441<br>City Centre G.P.O<br>00100 Nairobi<br>KENYA |

### Korea

|                |   |
|----------------|---|
| Sunny Air Inc. | #602, 54 Doryoung-ro<br>690-802 Jeju City, Jeju-do<br>REPUBLIC OF KOREA |
|----------------|---|

### Kyrgyzstan

|                 |  |
|-----------------|--|
| SKY KG Airlines | 1/9 Sumskey Lane<br>720005 Bishkek<br>KYRGYZSTAN |
|-----------------|--|

### Latvia

|   |   |
|---|---|
| Sia Baltijas Meridians  | 34 Araisu St.<br>1039 Riga, LATVIA      |
| Sia 'Profesionalais Sporta Aviacijas<br>Centrs Rigas Aeroklubs' | Lienes Street 1-17<br>1009 Riga, LATVIA |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
19/37



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Libya

|                                 |   |
|---------------------------------|---|
| Air Kufra<br>Iron and Steel Co. | Street off airport road<br>Tripoli, LIBYA |
|---------------------------------|---|

### Lithuania

|                         |  |
|-------------------------|--|
| AeroDiesel Baltics, UAB | Vytenio 50<br>03225 Vilnius, LITHUANIA |
| UAB 'AeroEkspresas'     | Vytenio 50<br>03229 Vilnius, LITHUANIA |

### Madagascar

|            |   |
|------------|---|
| Aeromarine | Hangar Aeromarine<br>Zone Avion Léger<br>Aéroport International Ivato<br>Antananarivo, MADAGASCAR |
|------------|---|

### Malaysia

|                          |   |
|--------------------------|---|
| APFT Engineering Sdn Bhd | Hangar Complex,<br>Sultan Ismail Petra Airport<br>Pengkalan Chepa<br>16100 Kota Bharu, Kelantan<br>MALAYSIA |
| CTRM Aviation SDN BHD    | Composites Technology City<br>Batu Berendam Airport<br>75350 Melaka<br>MALAYSIA                             |
| PRIMA AIR SDN BHD        | Jalan Kuala Muda<br>Padang Matsirat<br>07100 Langkawi, Kedah Darul Aman<br>MALAYSIA                         |



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Malta

|                               |   |
|-------------------------------|---|
| Falcon Aviation Engineering   | Security Gate 1<br>Malta Internationale Airport<br>LQA 4000 Luqa, MALTA |
| Maintenance Centre Malta Ltd. | Hangar 6, Gate 2<br>Malta International Airport<br>LQA 9023 Luqa, MALTA |

### Moldova

|   |   |
|---|---|
| Flight Control Systems s.r.l.<br>Yury Mitrofansky | Str. Sarmizegetusa 15, of. 302-a, b<br>2060, mun. Chisinau<br>REPUBLIC OF MOLDOVA |
|---|---|

### Morocco

|              |   |
|--------------|---|
| MDS Aviation | Aéroport de Rabat-Salé<br>Rabat, MOROCCO  |
| RAM Academy  | Aéroport Casa-Anfa<br>Casablanca, MOROCCO |

### Netherlands

|   |   |
|---|---|
| Aero Service B.V.                                 | Emoeweg 24-26<br>8218 PC Lelystad, NETHERLANDS        |
| ATN Aircraft Division                             | 7903 BE Hoogeveen<br>Plesmanstraat 10, NETHERLANDS    |
| Aviation Maintenance Rotterdam                    | Zaventembaan 1<br>3045 AR Rotterdam, NETHERLANDS      |
| Aviation Technics B.V.                            | De Zanden 31-33<br>7395 Pa Teuge Airport, NETHERLANDS |
| Cycloon Holland B.V.                              | Olivier van Nortweg 9<br>5928 LX Venlo, NETHERLANDS   |
| General Enterprises B.V.                          | Machlaan 8°<br>9761 TK Eelde, NETHERLANDS             |
| International Aviation Support bv                 | De Zanden 113<br>7395 PG Teuge, NETHERLANDS           |
| KN Singles and Twins<br>Aviation Consultants B.V. | Flamingoweg 12<br>8218 NW Lelystad, NETHERLANDS       |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
21/37



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                       | Adress   |
|----------------------------|--|
| Rijnmond Air Services B.V. | Rotterdam Airportplein 54<br>3045 AP Rotterdam, NETHERLANDS        |
| Transal Aero Services B.V. | Calandweg 2 E<br>4341 RA Arnemuiden, NETHERLANDS                   |
| Vliegwerk Holland B.V.     | Zeeland Airport Calandwag 50-56<br>4341 RA Arnemuiden, NETHERLANDS |
| Wings Over Holland B.V.    | Emoeweg 28<br>8218 PC Vliegveld Lelystad, NETHERLANDS              |

### New Zealand

|                   |  |
|-------------------|--|
| Aeromotive Ltd    | Steele Road R.D. 2<br>Hamilton Airport<br>2001 Hamilton, NEW ZEALAND |
| Airwork (NZ) Ltd. | Ardmore Airfield<br>Papakura<br>Auckland, NEW ZEALAND                |

### Nigeria

|                                |  |
|--------------------------------|--|
| International Aviation College | Ilorin International Airport<br>P.M.B. 1395 Ilorin, Kwara State<br>NIGERIA |
| PICOMSS Nigeria                | Benin Airport<br>Benin, NIGERIA  |

### Norway

|                       |  |
|-----------------------|--|
| Aeromech A/S          | Smaflyhavna<br>2007 Kjeller, NORWAY                            |
| Air Service Eggemoen  | Flyplassveien 24<br>Eggemoen Airfield<br>3514 Hønefoss, NORWAY |
| N.a.c. Maintenance AS | Bardufoss Lufhavn<br>9325 Bardufoss, NORWAY                    |
| Tromso Flyklubb       | Tromso Airport Postb. 2145<br>9267 Tromso, NORWAY              |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
22/37

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Pakistan

|                                 |  |
|---------------------------------|--|
| Hybrid Technics Private Limited | F-9 Walton Airport<br>54000 Lahore, Punjab<br>PAKISTAN |
|---------------------------------|--|

### Philippines

|   |  |
|---|--|
| Adventure Flight Education and Sports, Inc. | Hangar No. 6, General Aviation Area<br>Mactan Int. Airport<br>6015 Lapu-Lapu City, Cebu<br>REPUPLIC OF THE PHILIPPINES |
|---|--|

|                                  |   |
|----------------------------------|---|
| Asian Aeronautics Services, Inc. | Manual A. Roxas Highway<br>Clark Special Economic Zone<br>2009 Clark Field, Pampanga<br>REPUPLIC OF THE PHILIPPINES |
|----------------------------------|---|

|                         |   |
|-------------------------|---|
| Aviation Hub Asia, Inc. | Hangar 3<br>C/O Omni Aviation Complex<br>Manuel A. Roxas Highway<br>2009 Clark Field, Pampanga<br>REPUBLIC OF THE PHILIPPINES |
|-------------------------|---|

|                     |  |
|---------------------|--|
| PPI Consulting Inc. | BLDG 8324<br>Subic Bay International Airport<br>2200 Subic Bay Freeport Zone,<br>REPUBLIC OF THE PHILIPPINES |
|---------------------|--|

### Poland

|                         |   |
|-------------------------|---|
| Aero Club Spólka z.o.o. | Obory 100<br>05-510 Konstancin Jeziorna, POLAND |
|-------------------------|---|

### Portugal

|                  |   |
|------------------|---|
| Aerotecnica, LDA | Aerodromo Municipal de Cascais-Tires<br>2785-632 San Domingos de Rana, PORTUGAL |
|------------------|---|

|                               |   |
|-------------------------------|---|
| CAE Global Academy Evora S.A. | Aerodrome Municipal de Evora<br>Estrada de Viana, Apartado 33<br>7002 – 501 Evora, PORTUGAL |
|-------------------------------|---|

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
23/37



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Qatar

|                            |                            |
|----------------------------|----------------------------|
| Qatar Aeronautical College | PO Box 4050<br>Doha, QATAR |
|----------------------------|----------------------------|

### Romania

|                     |   |
|---------------------|---|
| Primul Meridian SRL | Vintila Voda Street, No 50<br>230000 Slatina, Old County<br>ROMANIA |
|---------------------|---|

|                              |  |
|------------------------------|--|
| Regional Air Services S.R.L. | Aerodrom Tuzla<br>907295 Tuzla, Constanta<br>ROMANIA |
|------------------------------|--|

### Russia

|                                    |   |
|------------------------------------|---|
| JSC "Ural Works of Civil Aviation" | Belinskogo 262 M,<br>620089 Jekaterinburg, RUSSIA |
|------------------------------------|---|

|                    |   |
|--------------------|---|
| Rodina Technic JSC | Big Gruszinskaya<br>Street House 40/1, Office 32<br>123056 Moscow, RUSSIA |
|--------------------|---|

|                 |   |
|-----------------|---|
| Sky Service LLC | Proezd Stroiteley, 1<br>140500 Lyhovitsy City, RUSSIA |
|-----------------|---|

### Slovakia

|                        |   |
|------------------------|---|
| SEAGLE AIR-FTO, s.r.o. | Zahumenska 6672/60<br>91104 Trencin, SLOVAKIA |
|------------------------|---|

### Slovenia

|               |   |
|---------------|---|
| Avtohisa Meze | Matjaz Meze S.P.<br>Lancovo 10 E<br>4240 Radovljica, SLOVENIA |
|---------------|---|

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

Page  
24/37



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                              | Adress  |
|-----------------------------------|---|
| <b>South Africa</b>               |   |
| CitiJet Air Charter (Pty) Ltd.    | Hangar No. 35<br>Lanseria Intl. Airport<br>Lanseria<br>REPUBLIC OF SOUTH AFRICA                                     |
| Diesel Aviation Service Center    | 33 Hangar<br>Rand Airport<br>1419 Germiston<br>REPUBLIC OF SOUTH AFRICA   |
| Kingfisher Aviation (Pty) Ltd.    | 19 Drommedaris Str.<br>7140 Gordons's Bay,<br>REPUBLIC OF SOUTH AFRICA  |
| National Airways Corp. (Pty) Ltd. | Hanger 104 C Gate 15<br>Lanseria Airport<br>1748 Lanseria,<br>REPUBLIC OF SOUTH AFRICA                              |
| Nevergreen Aircraft Industries    | Northern Perimeter Road<br>Safair Complex<br>Kempton Park<br>1620 Johannesburg, Gauteng<br>REPUBLIC OF SOUTH AFRICA |
| Placo Pty Ltd.                    | PO Box 18017<br>Rand Airport<br>1419 Germiston,<br>REPUBLIC OF SOUTH AFRICA   |
| Plane Maintenance Facility cc     | Hangar W5, Gate 5<br>Lanseria Airport<br>Lanseria<br>REPUBLIC OF SOUTH AFRICA                                       |
| Wingman Aircraft Maintenance      | Hangar 'O' Grand Central Airport<br>New Road<br>Midrand<br>REPUBLIC OF SOUTH AFRICA                                 |



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Spain

|                              |   |
|------------------------------|---|
| Aircrafttech S.L.            | Apartado 115<br>Hangar 7<br>17487 Empuriabrava<br>SPAIN   |
| Dédalo Aviacion S.L.         | AERODROMO de Requena - Hangar 2<br>Autovia A3, KM 297<br>46391 Requena, Valencia<br>SPAIN       |
| Futurhangars SL              | Hangar 13b -14b Zona Norte<br>Aeropuerto de Sabadell<br>08205 Sabadell<br>SPAIN                 |
| Malaga Air Maintenance S.L.  | C/ Carril de la Cordobesa, 40<br>29003 Malaga<br>SPAIN  |
| Roeder Ibérica S.L.U.        | Aeropuerto de Cuatro Vientos,<br>Carretera del Barrio de la Fortuna 10<br>28054 Madrid<br>SPAIN |
| Rosique Clasicos Aircraft SL | 46 Cami De L´Aleixar 7-2<br>43201 Reus-Tarragona<br>SPAIN                                       |

### Sweden

|                              |  |
|------------------------------|--|
| Air Service Göteborg         | Göteborg City Airport<br>42373 Säve, SWEDEN    |
| Air Service Göteborg AB      | Skogsvägen 61<br>43538 Mölnlycke, SWEDEN       |
| Aviation Maintenance Service | Engelholms Airport<br>26291 Engelholm, SWEDEN  |
| Avico Aviation               | Sörviken 135<br>83498 Brunflo, SWEDEN          |
| Helicraft Nordflygservice AB | Eskilstuna Airport<br>63506 Eskilstuna, SWEDEN |
| IAPS                         | Uppvindsvögen 20<br>58274 Lindköping, SWEDEN   |
| LTHF-Aviation                | Box 215<br>24123 Eslöv, SWEDEN                 |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page  
26/37**



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                                    | Adress                                   |
|---|--|
| Norden Aerotech Västerås AB             | Hässlögatan 8<br>72131 Västerås, SWEDEN  |
| Ost Flyg / Diamond Aircraft Scandinavia | Asvägen 23<br>39365 Kalmar, SWEDEN       |
| Scandinavian Airtech AB                 | Hässlögatan 20<br>72131 Västerås, SWEDEN |
| Täby Air Maintenance AB                 | Örebro Airport<br>70594 Örebro, SWEDEN   |
| Z Airtech                               | Byggnad 83 F4<br>83296 Fösön, SWEDEN     |

### Switzerland

|  |  |
|--|--|
| Aeromeccanica SA                                   | Aeroporto Cantonale Locarno<br>6569 Gordola, SWITZERLAND             |
| Airmatec   | Flughafenstrasse 19<br>Flughafen Bern-Belp<br>3123 Belp, SWITZERLAND |
| Fliegerschule Birrfeld AG<br>Technischer Betrieb   | Flugplatz Birrfeld<br>5242 Lupfig, SWITZERLAND                       |
| Flight Maintenance MFGZ<br>General Aviation Center | Flughafen Zürich<br>8058 Zürich – Flughafen, SWITZERLAND             |
| Lüthl Bernhard<br>ZSW/Präz. Mechanik               | Dornhaldestrasse 51<br>3627 Heimberg, SWITZERLAND                    |
| Mecanair SA  | Rte de l'Aerodrome 30<br>1730 Ecuwillens, SWITZERLAND                |
| Motorfluggruppe Thurgau                            | Flugplatz<br>9506 Lommis, TG, SWITZERLAND                            |
| Ruag Aerospace                                     | Via Aeroporto<br>6982 Agno, SWITZERLAND                              |
| Skyparts GmbH                                      | Flugplatz<br>8915 Hausen am Albis, SWITZERLAND                       |



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Thailand

|                                     |   |
|-------------------------------------|---|
| Asian Aerospace Services Ltd.       | 25th Flr, Chamnan Phenjati Business Center Bldg,<br>68 / 209 Rama 9 Rd, Huaykwang<br>1320 Bangkok<br>THAILAND |
| Civil Aviation Training Center      | 1032/355 Phaholyothin Road<br>Jompol<br>10900 Jatujak, Bangkok<br>THAILAND                                    |
| Northern Aviation Services Co. Ltd. | Saha Group Industrial Park<br>304 Moo 1, A Bueng<br>20230 Sri Racha, Choburi,<br>THAILAND                     |

### Tunisia

|  |                                 |
|--|---------------------------------|
| AFA – Airline Flight Academy<br>Centre Makni | Menzah 9<br>2092 Tunis, TUNISIA |
|--|---------------------------------|

### Turkey

|   |  |
|---|--|
| AFA – Atlantic Flight Academy                       | Barbaros Hayrettin Pasa MH. 1992,<br>SK. NO: 14 KAT 3<br>34522 Esenyurt-Istanbul, TURKEY |
| Ayjet Anadolu Yildizlari<br>Mehmet Akif Cad.        | Mehmet Çibikçi Is Merkezi<br>No:2 Kat:7 D:15-16<br>34188 Sirinevler-Istanbul, TURKEY     |
| Top Service A.S.                                    | Ataturk Havalimani<br>E Kapisi<br>34630 Sefakey / Istanbul, TURKEY                       |
| Turkish Airlines Technic Inc.<br>Maintenance Center | Ataturk Airport<br>34819 Yesilkoy Istanbul, TURKEY                                       |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
28/37

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name | Adress |
|------|--------|
|------|--------|

### Ukraine

|  |  |
|--|--|
| Challenge Aeroport Ltd.                              | 103, Stolichnoe shosse<br>03131 Kiev, UKRAINE      |
| International Joint-Stock<br>Aviation Company "Urga" | Dobrovolsky Street 1a<br>25005 Kirovograd, UKRAINE |
| LLC Rotor Ukraine                                    | 51 Lenina Avenue<br>54029 Mykolaiv, UKRAINE        |
| Mars RK Ltd.   | Volynska Str. 66-A<br>03286 Kiev, UKRAINE          |

### United Arab Emirates

|                                      |  |
|--------------------------------------|--|
| Fujairah Aviation Academy            | Fujairah International Airport<br>PO Box 777<br>Fujairah, UNITED ARAB EMIRATES |
| Horizon International Flight Academy | Ai Ain International Airport<br>Al Ain, UNITED ARAB EMIRATES                   |

### United Kingdom

|                                   |  |
|-----------------------------------|--|
| Aeros Engineering Ltd.            | Hangar Se 16<br>Gloucestershire Airport<br>GL51 6SP Cheltenham, Gloucestershire, UNITED KINGDOM                      |
| Aerotech Aircraft Maintenance LTD | Airpark, Coventry Airport,<br>Rowley Road, Baginton<br>CV3 4FR Coventry, UNITED KINGDOM                              |
| Air Nimbus                        | The Business Centre<br>Llangarron<br>HR9 6 PG Herefordshire, UNITED KINGDOM  |
| Airspeed Aviation Ltd.            | Derby Airfield<br>Hilton Road<br>DE65 6GU Derby, UNITED KINGDOM  |
| Apollo Aviation Advisory Ltd.     | Concorde House<br>24 Cecil Pashley Way, Shoreham<br>Airport, Shoreham-by-Sea<br>BN43 5FF West Sussex, UNITED KINGDOM |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**29/37**

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name   | Adress   |
|--|--|
| Aviation Maintenance Ltd.                                    | Building 237<br>Eastern Sector, Bournemouth<br>International Airport<br>BH23 6NE Christchurch, Dorset, UNITED KINGDOM                      |
| BCT Aviation Maintenance LTD<br>Cardiff Aviation Engineering | Wings Hangar<br>Cardiff International Airport<br>CF62 3BD Vale of Glamorgan, Wales, UNITED KINGDOM   |
| BIH (ONSHORE) Ltd.   | Anson House<br>Coventry Airport<br>CV8 3AZ Coventry, UNITED KINGDOM  |
| Bristol Flying Centre  | Bristol International Airport<br>BS48 3DP Bristol, UNITED KINGDOM  |
| Channel Island Aero Services Ltd.<br>(Engineering)           | Aero Club Hangar<br>States Airport<br>JE3 7BP Jersey, Channel Islands, UNITED KINGDOM  |
| CSE Aviation   | Oxford Airport, Kidlington<br>OX5 1RA Oxford, UNITED KINGDOM   |
| Deltair Airmotive Ltd.                                       | 17 Aston Road<br>Waterlooville<br>PO7 7XG Hants, UNITED KINGDOM  |
| Diamond Aircraft U.K. Ltd.                                   | Hangar 62B<br>Eastern Business Park<br>Bournemouth International Airport<br>BH23 6NE, Christchurch, Dorset, UNITED KINGDOM                 |
| Diamond Executive Aviation                                   | Gamston / Retford Airport<br>DN22 0QL Nottinghamshire, UNITED KINGDOM  |
| DS Worldwide (Civil) Aviation Ltd.                           | Hangar 603<br>Eastern Business Park<br>Bournemouth International Airport<br>Christchurch<br>BH23 6NE, Christchurch, Dorset, UNITED KINGDOM |
| Fast Aviation Ltd.   | Hangar 237<br>Bournemouth International Airport<br>BH23 6NE, Christchurch, Dorset, UNITED KINGDOM  |
| Flight Composites<br>c/o Southern Sailplanes                 | Membury Airfield<br>RG17 7TJ Hungerford, Berkshire, UNITED KINGDOM   |
| Goodwood Road Racing Co.Ltd<br>Aircraft Engineering Division | Goodwood Aerodrome<br>PO18 0PH Chichester, West Sussex, UNITED KINGDOM   |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**30/37**



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name  | Adress  |
|---|---|
| London Elstree Aviation Ltd.                          | London Elstree Aerodrome<br>WD6 3AR Hertfordshire, UNITED KINGDOM   |
| MCA Aviation Ltd.                                     | Hangar 603,<br>Aviation Park North East<br>Bournemouth International Airport<br>BH23 6NE Dorset, UNITED KINGDOM |
| Multiflight Ltd.                                      | South Side Aviation Centre<br>Leeds Bradford International Airport<br>LS19 7UG Leeds, UNITED KINGDOM            |
| Namair Light Aircraft Maintenance                     | Draycot Aerodrome<br>Chiseldon, Swindon<br>SN4 0HX Wiltshire, UNITED KINGDOM                                    |
| Ravenair Liverpool<br>Business Aviation Centre        | John Lennon Airport<br>L24 5GA Liverpool<br>UNITED KINGDOM  |
| Redhill Air Services Ltd. /<br>Airworks Services Ltd. | Blister Hangar, Crabhill Lane<br>Redhill Aerodrome<br>RH1 5PG Redhill, Surrey, UNITED KINGDOM                   |
| RGV Aviation Ltd.                                     | Hangar SE40<br>Gloucestershire Airport<br>GL51 6SP Cheltenham, UNITED KINGDOM                                   |
| Shropshire Light Aviation                             | 'A' Hangar<br>Sleap Airfield, Harmer Hill<br>SY4 3HE Shrewsbury, UNITED KINGDOM                                 |
| Silverstar Maintenance Services Ltd.                  | Hangar 8<br>Blackpool International Airport<br>FY4 2QY Blackpool, Lancashire, UNITED KINGDOM                    |
| Stapleford Flying Club Ltd.                           | Stapleford Aerodrome<br>Stapleford Tawney<br>RM4 1SJ Essex, UNITED KINGDOM                                      |
| Tayflite (Engineering) Ltd.                           | Hangar 2<br>Perth Airport, Scone<br>PH2 6PL Perth, UNITED KINGDOM   |
| Tayside Aviation Ltd.                                 | Dundee Airport<br>Riverside Drive<br>DD2 1UH Dundee, UNITED KINGDOM   |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
31/37

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                        | Adress  |
|-----------------------------|---|
| White Waltham Airfield Ltd. | Waltham Road<br>Maidenhead<br>SL6 3NJ Berkshire, UNITED KINGDOM |

| <b>USA</b>  |  |
|---|--|
| A & M Maintenance Services, Inc.                    | 134 S. Clow Int'l Parkway<br>Suite B<br>60490 Bolingbrook / Illinois, USA                        |
| Absolute Aero Inc.<br>dba Absolute Aero Maintenance | 22005 Skywest Dr.<br>94541 Hayward / California, USA   |
| Advanced Aircraft Services                          | 500 Airport Rd. Suite D<br>17543 Lititz / Pennsylvania, USA                                      |
| Aero Experts, LLC                                   | 6720 S Plumer Ave<br>85706 Tucson / Arizona, USA   |
| Aero Restorations, Inc.                             | 4660 Jimmy Doolittle Drive<br>Addison Airport<br>75001 Addison / Texas, USA                      |
| Africair, Inc.                                      | 13691 SW 145th Court<br>FL 33186 Miami / Florida, USA  |
| Ahart Aviation Services                             | 186 Airway Blvd<br>94551 Livermore / California, USA   |
| Air Shasta Rotor & Wing Inc.                        | 3770 Flight Ave<br>96002 Redding, CA, USA  |
| Alpine Aviation, Inc.                               | 13310 Nevada City Ave<br>95945 Grass Valley / California, USA<br>Apteryx, Inc. d/b/a             |
| Angel City Flyers                                   | 2901 E Spring St. Suite A/B<br>90806 Long Beach / California, USA                                |
| AP Aeronautics Inc.                                 | 1900 Joe Crosson Dr.<br>92020 El Cajon / California, USA   |
| Arapahoe Aero                                       | 12760 East Control Tower Road,<br>Box K-1, Centennial Airport<br>80112 Englewood / Colorado, USA |
| Arlins Aircraft Service                             | 36 Gallatin Field<br>59714 Belgrade / Montana, USA   |
| ASI Jet AG, LLC                                     | 1710 Butterfield Dr.<br>55350 Hutchinson / Minnesota, USA  |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**32/37**





Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name   | Adress  |
|--|---|
| Atlantic Aviation – Phoenix                    | 732 W. Deer Valley Rd.<br>85027 Phoenix / Arizona, USA                                  |
| Aurora Flight Sciences                         | 9950 Wakeman Drive<br>20110 Manassas / Virginia, USA                                    |
| BMV Air Center                                 | 701-2 NE 10th St,<br>33060 Pompano Beach / Florida, USA                                 |
| Bohlke International Airways                   | Rural Route 2<br>Henry E. Rohlsen Airport<br>00850 St. Croix / U.S. Virgin Islands, USA |
| BP Air, Inc.                                   | 70 Stacy Haines Rd.<br>08048 Lumberton / New Jersey, USA                                |
| Brunetto Flying Service                        | 13053 N. 69th St.<br>85254 Scottsdale / Arizona, USA                                    |
| Central Flying Service, Inc.                   | 1501 Bond Street<br>72202 Little Rock / Arkansas, USA                                   |
| CFDI Aero                                      | 4700 Spartan Drive Hangar 102<br>76207 Denton / Texas, USA                              |
| Clay Lacy Aviation                             | 8285 Perimeter Road South,<br>98108 Seattle / Washington, USA                           |
| Cochise College                                | 4190 W State HWY 80<br>85607 Douglas / Arizona, USA                                     |
| Columbia Air Services – BHB LLC                | 112 Caruso Dr.<br>04605 Trenton / Maine, USA  |
| Columbia Air Services, Inc.                    | 175 Tower Ave.<br>06340 Groton / Connecticut, USA                                       |
| CopaAir Maintenance Services Inc.              | 20590 SW Citrus Blvd<br>34956 Indiantown, FL, USA                                       |
| CP Aviation Services                           | 8000 Airport Road, Unit 12<br>88008 Santa Teresa / New Mexico, USA                      |
| Daytona Aircraft Services Inc.                 | 561 Pearl Harbor Drive<br>32114 Daytona Beach / Florida, USA                            |
| dba American Avionics<br>Aviators Choice LLC   | 7023 Perimeter Rd. So.<br>98108 Seattle / Washington, USA                               |
| Diamond Flight Center of Spanish<br>Fork, L.C. | 2050 N. 300W.<br>Hangar 34<br>84660 Spanish Fork / Utah, USA                            |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

Page  
33/37

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name   | Adress   |
|--|--|
| Dixie Chopper Air LLC  | 102 Ballard LN<br>46135 Greencastle / Indiana, USA   |
| Embry-Riddle Aeronautical University<br>Fleet Maintenance Center | 600 South Clyde Morris Blvd.<br>32114 Daytona Beach / Florida, USA                           |
| Epic Aviation, Inc.  | 2022 Aero Circle<br>32168 New Smyrna Beach / Florida, USA                                    |
| Executive Air Transport Inc.                                     | 103 Sinclair Drive<br>49441 Muskegon / Michigan, USA   |
| Falcon Aviation Services   | 5 Falcon Dr.<br>30269 Peachtree City / Georgia, USA  |
| Fetter Aviation Co.  | 10399 Piscataway Road<br>20735 Clinton / Maryland, USA                                       |
| Fresh Air Cargo  | 2901 f East Spring St.<br>90806 Long Beach / California, USA                                 |
| Galvin Flying Services, Inc.                                     | 7149 Perimeter Road,<br>Boing Field<br>98108 Seattle / Washington, USA                       |
| Gibbs Service Center   | 8906 Aero Drive<br>92123 San Diego / California, USA   |
| Gorge Aviation Services LLC                                      | 45 Airport Way<br>98617 Dallesport / Washington, USA   |
| Gulf Coast Aviation  | New Orleans Lakefront Airport<br>5701 Walter Beech Rd.<br>70126 New Orleans / Louisiana, USA |
| Hawk Aviation LLC P.B.A.<br>U.S. Flight Aircraft Maintenance     | 136 Tower Rd.<br>10604 White Plains / New York, USA  |
| Horizon Aviation Services, Inc.                                  | 2801 Airport Rd.<br>23323 Chesapeake / Virginia, USA   |
| J.A. Air Center  | 3N060 Powis Rd.<br>60185 West Chigago / Illinois, USA  |
| JNW Enterprises LLC<br>d.b.a. Cornerstone Aviation LLC           | 1725 E St. NE<br>98002 Auburn, WA, USA   |
| Kansas City Aviation Center, Inc.                                | 15325 S. Pflumm Rd.<br>66062 Oltahe / Kansas, USA  |
| Keyson Airways Corporation                                       | 117 Perimeter Road<br>03063 Nashua / New Hampshire, USA                                      |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**34/37**

**Technify  
Motors**

Technify Motors GmbH  
 Platanenstrasse 14  
 09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
 Fax: +49 (37204) 696-2912  
 www.centurion.aero  
 info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                               | Adress  |
|------------------------------------|---|
| Landmark Aviation                  | 14600 N. Airport Drive<br>85260 Scottsdale / Arizona, USA                 |
| Landmark Aviation                  | 1001 Sycolin Road<br>20175 Leesburg / Virginia, USA                       |
| LeTourneau University              | 2100 S. Mobberly St.<br>75602 Longview / Texas, USA                       |
| Maine Aviation Sales Inc.          | 100 Yellow Bird Road<br>04102 Portland / Maine, USA                       |
| Michael VanderWal                  | 3064 Pine Creek Dr<br>98273 Mount Vernon / Washington, USA                |
| Midwest Aviation Center, LLC       | 525 Turbine Ave.<br>63005 Chesterfield / Missouri, USA                    |
| Midwest Avtech, Inc.               | 4241 Ed Urban Dr.<br>61354 Peru / Illinois, USA                           |
| Midwest Corporate Air, Inc.        | 3100 St. Rt. 47 West<br>43311 Bellefontaine / Ohio, USA                   |
| Mohawk Technologies, LLC           | 2633 Lantana Road<br>Suite 30, Hangar 402<br>33462 Lantana / Florida, USA |
| North American Jet Maintenance LLC | 1011 South Wolf Road<br>60090 Wheeling / Illinois, USA                    |
| North Star Aviation                | 3030 Airport Road<br>56001 Mankato / Minnesota, USA                       |
| Northern Air Inc.                  | 5500 44th St. S.E.<br>49512 Grand Rapids / Michigan, USA                  |
| Pacific Air Craft Inc.             | 41 Airpark Road<br>08540 Princeton / New Jersey, USA                      |
| Port City Air Inc.                 | 104 Grafton Drive<br>03801 Portsmouth / New Hampshire, USA                |
| Premier Aircraft Service, Inc.     | 5540 NW 23rd Avenue<br>BLDG 14<br>33309 Fort Lauderdale / Florida, USA    |
| Premier Jet Center                 | 14801 Pioneer Trail<br>55347 Eden Prairie / Minnesota, USA                |
| Pride Aviation Inc.                | 2955 Airport Road<br>29153 Sumter / South Carolina, USA                   |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
35/37

**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                                 | Adress   |
|--------------------------------------|--|
| Prime Planes Aircraft Services       | 111 Aviation Drive North<br>34104 Naples / Florida, USA                            |
| Propel Aviation Services, LLC        | 14300 S.W. 129 Street<br>Suite # 101<br>33186 Miami / Florida, USA                 |
| Sabena Airline Training Center, Inc. | 5010 E. Falcon Drive<br>85215 Mesa / Arizona, USA                                  |
| Sawyer Aviation, LLC                 | 15115 N. Airport Dr. #12<br>85260 Scottsdale / Arizona, USA                        |
| Shoreline Aviation Inc.              | 93 Old Colony Lane<br>02050 Marshfield / Massachusetts, USA                        |
| Sierra Mountain Aviation, Inc.       | 13308 Nevada City Ave<br>95945 Grass Valley / California, USA                      |
| SouthTec Aviation LLC                | Rowan County Airport<br>3670 Airport Loop<br>28147 Salisbury / North Carolina, USA |
| Southwest Flight Center              | 15041 N. Airport Dr. #103<br>85260 Scottsdale / Arizona, USA                       |
| Spartan College of Aeronautics       | 123 Cessna Drive<br>74115 Tulsa / Oklahoma, USA                                    |
| Sterling Aviation                    | 145 John Glenn Drive<br>94520-5606 Concord / California, USA                       |
| Streamline Aviation, LLC             | 4321 General Aviation Avenue<br>Hangar 1<br>78719 Austin / Texas, USA              |
| Take Flight Alaska                   | 1740 East Fith Avenue<br>99501 Anchorage / Alaska, USA                             |
| US Aviation Group LLC                | 4850 Spartan Drive<br>76207 Denton / Texas, USA                                    |
| Utah State University                | 2500 North 900 West<br>84321 Logan / Utah, USA                                     |
| Utah Valley State College            | 1185 Mike Jense Parkway<br>84601 Provo / Utah, USA                                 |
| Van Bortel Aircraft, Inc.            | 4912 South Collins<br>76018 Arlington / Texas, USA                                 |
| Van Nuys Flight Center               | 16700 Roscoe Blvd.<br>91406 Van Nuys / California, USA                             |

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**36/37**



**Technify  
Motors**

Technify Motors GmbH  
Platanenstrasse 14  
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0  
Fax: +49 (37204) 696-2912  
www.centurion.aero  
info@centurion.aero

## Technische Mitteilung / Service Bulletin

**Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 68 / 15.06.2017  
**Service Bulletin No. / Date** TM TAE 000-0003, Revision 68 / June 15, 2017

| Name                                 | Adress  |
|--------------------------------------|---|
| West Coast Aircraft Maintenance, LLC | 2881 E. Spring St.<br>90806 Long Beach / California, USA          |
| West Valley Aircraft Services, LLC   | 1901 Embarcadero Rd. Ste 100<br>94303 Palo Alto / California, USA |
| Winner Aviation Corporation          | 1453 Youngstown-Kingsville Rd.<br>44473-9797 Vienna / Ohio, USA   |

### Venezuela

|  |   |
|--|---|
| Aviaservice, C.A.  | Hangar Aviaservice<br>Aeropuerto de Caracas<br>"Oscar Machado Zuloaga"<br>1210 Charallave, Estado Miranda<br>VENEZUELA          |
| INAC – National Institute of Civil Aviation of Venezuela | Av. Jose Felix Sosa with Av. Luis Roche<br>Torre Britanica de Seguros 2-8 Floors<br>1060 Caracas, State of Miranda<br>VENEZUELA |

**Zulassung:** Die technischen Informationen, die in diesem Dokument enthalten sind, wurden im Rahmen der Befugnisse der EASA- Genehmigung als Entwicklungsbetrieb Nr. EASA.21J.010 genehmigt.  
**Approval:** The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval no. EASA.21J.010.

**Ersetzt Technische Mitteilung Nr. / Datum:** TM TAE 000-0003, Revision 67 / 10.05.2017  
**Replaces Service Bulletin No. / Date:** TM TAE 000-0003, Revision 67 / May 10, 2017

**Page**  
**37/37**