



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Betrifft: Autorisierte Wartungsbetriebe
Subject: authorized maintenance organisations

Betroffenes Luftfahrtgerät: alle Technify Motors GmbH Produkte
Type affected: all Technify Motors GmbH products

Betroffene Geräte-Nr.: alle
Models affected: all

Einstufung: Kategorie 5 – nur zur Information
Compliance: Category 5 – for information only

Dringlichkeit: sofort
Accomplishment: immediately

Grund: Wartungsarbeiten dürfen nur von Personen durchgeführt werden, die durch die zuständige Luftfahrtbehörde zur Durchführung dieser Arbeiten berechtigt wurden.

Reason: Maintenance work should only be performed by persons authorized through the competent authority of the respective country.

Maßnahmen: Personen sind durch die zuständige nationale Luftfahrtbehörde des jeweiligen Landes berechtigt oder zertifiziert Wartungsarbeiten durchzuführen.
Um einen hohen Qualitätsstandard für unser Produkt zu gewährleisten empfiehlt Technify Motors GmbH den Betreibern dringend, bei der Durchführung von Wartungsarbeiten, nur die Service-Center zu nutzen, welche in diesem Service Bulletin aufgeführt sind.

Correction: Persons are authorized or certificated to perform maintenance by the competent national authority of the respective country. In order to ensure a high quality standard for our product, Technify Motors GmbH strongly recommends that operators only utilize the service-center described in this service bulletin when performing maintenance.

Hinweise: Die durch die zuständige Behörde erteilte Genehmigung als Instandhaltungsbetrieb, bleibt durch die Empfehlung der Technify Motors GmbH unberührt und wird insbesondere nicht automatisch erweitert.

Technify Motors GmbH empfiehlt folgende Instandhaltungsbetriebe:

Remarks: The approval granted by the competent authority as a maintenance organization remains unaffected by the recommendation of Technify Motors GmbH and is not extended automatically.

Technify Motors GmbH recommends the following maintenance organizations:



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

Armenia

Armenia Airways	Ave. Azatutyan Bld. 12/1 Office 18 0014 Yerevan ARMENIA
-----------------	--

Australia

Aircraft Engineers Associates PTY LTD	Hangar 2, Beatty Road Archerfield Airport 4108 AUD-Queensland AUSTRALIA
CGG Aviation (Australia) Pty Ltd.	Hanger 106 10 Compass Road 6164 Jandakot Airport, WA AUSTRALIA
East Coast Aviation Pty Ltd	Latrobe Regional Airport 75 Airfield Road 3844 Traralgon, VIC AUSTRALIA
Phoenix Aviation	4 Murphy Court, Darwin International Airport PO Box 41119 0811 Casuarina Northern Territory, AUSTRALIA
Sport Air Services c/o Australian Wings Academy	19 Loes Bonney Circuit 4225 Bilinga Gold Coast Airport AUSTRALIA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

Austria

AAC Austrian Aircraft Corp. Oest. LFZ GmbH	Flughafen Linz 4063 Hoersching, AUSTRIA
AAC Austrian Aircraft Corp. Oest. LFZ GmbH	Flughafen Graz 8073 Feldkirchen, AUSTRIA
Diamond Aircraft Industries GmbH	N.A. Ottostrasse 5 2700 Wiener Neustadt, AUSTRIA
Flugsportzentrum Tirol	Kranebitter Allee 105 6020 Innsbruck, AUSTRIA
HB-Flugtechnik GmbH	Dr. A. Schärfstr. 42 4053 Haid, AUSTRIA
Luftfahrzeug Wartungsbetrieb Krems GmbH	Flughafenstraße 19 3500 Krems, AUSTRIA
Luftfahrzeugtechnik Zell am See GmbH & Co. KG	Kaprunerstrasse 15 5700 Zell am See, AUSTRIA
Urbe Aero GmbH	Ferdinand Graf v. Zeppelinstraße 11 2700 Wiener Neustadt, AUSTRIA

Azerbaijan

SW Helicopter Services LLC	Zabrat-2 settlement Airport Baku, AZ1104, AZERBAIJAN
----------------------------	--

Bangladesh

Arirang Aviation Limited (A Youngone Company)	Arirang Hangar Complex, General Aviation Area Hazrat Shahjalal International Airport 1229 Kurmitola, Dhaka, BANGLADESH
TAC Aviation Ltd.	Osmani International Airport Sylhet, BANGLADESH



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

Belgium

Abelag	Luchthavenlei 1 Bus 66 2100 Antwerpen, BELGIUM
Aero Maintenance	Chaussee de Nivelles 167 7181 Arquennes, BELGIUM
BVBA Gill Aviation	Vliegheid 60 8560 Wevelgem, BELGIUM
Styl Aviation	PB 34 - Loods 5 Airport Antwerp 2100 Deurne / Antwerp, BELGIUM
Winters Aviation bvba	Leuchthavenlei 1 Bus 48 2100 Deurne, BELGIUM

Belize

Tropic Air Limited	Coconut Drive San Pedro Town, BELIZE
--------------------	---

Bermuda

Longtail Aviation International Limited	6 Southside Road DD03 St. Georges BERMUDA
---	---

Botswana

Northern Air Maintenance (Pty.) Ltd.	Private Bag 159 Maun, BOTSWANA
--------------------------------------	-----------------------------------

Brazil

TAM Aviacao Executiva e Táxi Aéreo S.A.	Av. Emilio Antonon s/n - Lote 1234 - Chacara Aeroporto JUNDIAI -SP 13212-010 BRAZIL
---	--



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Bulgaria	
Air Scorpio Ltd.	73 Persenk Str. 1164 Sofia, BULGARIA
Bluewind Aviation Ltd.	1 Brussels bul, building no. 5 1540 Sofia, BULGARIA
Bulgarian Aeronautical Center	Sofia Airport 1540 Sofia, BULGARIA
DEDALUS Aviation Services	LESNOVO Airport 2119 Sofia, BULGARIA

Canada	
Anderson Aviation (2002) Ltd	20 Wayne Hicks Lane S7L 6S2 Saskatoon, SK CANADA
Avworks Aerospace	A3-349 Noorduyn Park CALGARY AB T32-357 CANADA
Black Hawk Aviation Ltd.	426 Player Crescent S0K 4S1 Warman, Saskatchewan CANADA
CanWest Aerospace Inc.	#10 -5225 216th Street BC V2Y 2N3 Langley CANADA
Chinook Aircraft Maintenance Ltd.	30720 Rotor Drive V2T 6H5 Abbotsford, British Columbia CANADA
Diamond Aircraft Industries Inc.	1560 Crumlin Sideroad N5V 1S2 London, Ontario CANADA
Firkus Aircraft Inc.	42206 Airport Road V2P 1A5 Chilliwack, British Columbia CANADA
Fly Genesis Inc.	PO Box 312 L9Y 3Z7 Collingwood, Ontario CANADA

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
5/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Halcyon Aviation	#3 – 4340 King Street Boundary Bay Airport V4K 5B3 Delta, British Columbia CANADA
Harrier Aviation Ltd.	220A 18799 Airport way V3Y 2B4 Pitt Meadows, British Columbia CANADA
Harvey Aviation Services Inc.	100 Rue #1, GOV 1L0 St-Honoré, Quebec CANADA
Klarenbach Aviation Ltd.	Unit E1, 333 Noorduyn Park T3Z 3S7 Calgary, Alberta CANADA
M.B. Aero Inc.	706 South Gate Rd. R1A 3P8 St. Andrews, Manitoba CANADA
Nason Aviation Inc.	12375 – 132 Street T5L 1P9 Edmonton, Alberta CANADA
Pacific Rim Aviation Academy	393-18799 Airport Way V6Y 2B4 Pitt Meadows, British Columbia CANADA
Safari Express Aircraft Maint. Ltd.	Boundary Bay Airport Unit 2 – 4340 King Street V4K 0A5 Delta, British Columbia CANADA
Saskatoon Ltd.	28 Airport Crescent, S7L 6G9 Saskatoon, Saskatchewan CANADA
Xu Aviation Ltd.	2537 Huron St. N5V 5J1 London, Ontario CANADA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
China	
AeroHawk Aircraft Engineering Co. Ltd.	Dagao Airport Zhanhua County, Binzhou 256800 Shangdong CHINA
Anhui Sky Aviation International Flight Academy	FeiXi district SenLin Avenue, No. 3 WenDa Group 231201 HeFei, AnHui CHINA
Aviation Leader General Aviation Co., Ltd	Shandong BinAo Aircraft Industries Binzhou City, Shandong Province CHINA
AVIC Flight Academy	38# Airport Road Changzhou District, Guangxi Province 543002 Wuzhou City CHINA
Bei Da Huang General Aviation Co.	No480-8 Songhua Street 154004 Jiamusi City, Heilongjiang Province CHINA
Beijing Hangdun Aircraft Maintenance Engineering Co., Ltd.	No. 324 West Palace Street, 065201 Yanjiao Town, Sanhe City, Hebei Province CHINA
Beijing Huan General Aviation Co., Ltd	Mafang Town Navigation Industry Base in Pinggu District Beijing CHINA
Beijing Wanrun General Aviation Co., Ltd.	room 3507-001 unit 1 no. 7 building changqingyuan, dongcheng district 100061 Beijing City CHINA
Chengdu Hot Aviation Technology Co., Ltd	No. 1186, Baicao Road, Hi-Tech West Zone, 611731 ChengDu, Sichuan CHINA
China Flying Dragon General Aviation Co. Ltd.	No. 16 Nanhai Street Pingfang District, Harbin Hei Long Jiang CHINA

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
7/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Civil Aviation University of China	No. 2892, JinBei Road Dongli District 300300 TianJin City CHINA
Guangdong Xiangtai General Aviation Co. Ltd.	Southern Airlines Pearl Hotel Shihuaxi Street No. 163 51900 Zhuhai city, Guangdong Provinc CHINA
Hainan Aciation Academy Co. Ltd.	Sanxia Airport 443007 City of Yichang, Hubei Province CHINA
Hubei Sky-Blue International Aviation Academy Co. Ltd.	24F Building A Optical Valley International Wuhan CHINA
Hunan Hanxing International Aviation Academy	Airport Avenue , No. 1 Linkong South Road Changsha Huanghua International Airport 41037 Changsha City Hunan Province CHINA
Jiangsu Ruizhong General Aviation Co. Ltd.	Dalu General Aviation Airport Zhenjiang New District 212000 Zhenjiang City, Jiangsu Province CHINA
Jilin First International Aviation Academy Co., Ltd	No. 1 Jian Xin road Economic-Technological Development Dristrict Jilin City CHINA
JinSheng General Aviation	Lao Dong South Rd, Northwest Aviation Building, 8 Layers, No 296 Xian City, Shaanxi Province, SN 29 CHINA
Liaoning Ruixiang General Aviation Co., Ltd.	Caihu Airfield, Faku County 110403 Shenyang, Liaoning Province CHINA
Ordos General Aviation Co, Ltd.	Yijin Huoluo Banner Airport 017200 Ordos City, Inner Mongolia, CHINA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Qingdao Jiutian International Flight Academy Co., Ltd.	6#, No 702 Shanhe Road, Chengyang District 266108 Qingdao, Shandong CHINA
Reetek United Aircraft Engineering Co., Ltd.	Room Dool, 5th Floor, Bldg. A Tianqu Business Hotel 100621 Beijing CHINA
Shaanxi Phoenix International Flying College Co Ltd.	Liupanshan Airport Guyuan, Ningxia CHINA
Shandong Bin Ao Aircraft Industries Co., Ltd.	Binzhou Dagao Hi-Tech Dev. Zone Zhanhua County, Binzhou 256 800 Shandong Province CHINA
Sichuan LongHao Flight Driving Training Co., LTD	22 Binjiang Road, Economic and Technological Development Zone 628000 Guang Yuan City CHINA
Xin Jiang Tian Xiang Aviation College	Three North Road No. 110, Bo Hua Hotel Shi He Zi, Xin Jiang CHINA
Zhiyuan General Aviation Co., Ltd	No.1 Airport Road Handan Airport, Handan City 056006 Hebei Province CHINA

Colombia

Escuela de Aviacion de los Andes Aeroandes S.A.	Autopista Norte km 16 Aeropuerto Guaymaral Bogota, COLOMBIA
Tresa Ltda	Aeropuerto Guaymaral Int. 1 Bogota, COLOMBIA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

Cook Islands

Air Rarotonga Ltd.	Rarotonga International Airport Rarotonga, COOK ISLANDS
--------------------	--

Croatia

Diamond Aircraft Croatia d.o.o.	M.P. Miskine 72 42000 Varazdin, CROATIA
---------------------------------	--

Cyprus

Pegasus Flight Center Ltd.	Larnaca International Airport Larnacy, CYPRUS
----------------------------	--

Czech Republic

Aeroklub Ceske Republiky Aeroclub of the Czech Republic	U Mlýna 3 14100 Praha 4-Sporilov CZECH REPUBLIC
Air Jihlava – Service s.r.o.	Hencov 61 586 01 Jihlava CZECH REPUBLIC
EEA Tech spol. s.r.o.	Stare Mesto 310 56932 Stare Mesto CZECH REPUBLIC
Herbst Aero a.s.	Karkulinova 27 62000 Brno CZECH REPUBLIC
OK AVIATION Services s.r.o.	Drásov 201 26101 Příbram CZECH REPUBLIC
TomiAIR s.r.o.	Galandova 1241/19 16300 Praha 6 CZECH REPUBLIC



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

Denmark

Air Service International A/S	Stratusvej 1 7190 Billund, DENMARK
Airservice Vamdrup AP	Lufthavnsvej 7A 6580 Vamdrup, DENMARK
Billund Air Center A/S	Stratusvej 15 7190 Billund, DENMARK
General Aviation Service ApS	Solhoejgaardsvej 6 4000 Roskilde, DENMARK
North Flying A/S	Lufthavnsvej 100 Aalborg Airport 9400 Norresundby, DENMARK
UNI-FLY A/S	Hans Christian Andersen Airport Lufthavnvej 131, HG37 5270 Odense N, DENMARK

Ecuador

ARICA Aeroservicios Generales C.A.	Av. De las Américas, Aeropuerto Simon Bolivar, Hangar 7 Guayaquil, ECUADOR
---------------------------------------	--

Egypt

Egyptian Aviation Academy	6 October Airport El-wahat Road Giza, EGYPT
---------------------------	---

Ethiopia

Abyssinian Flight Services	P.O. Box 7716 Woreda 18, Kebele 36 House 174/01 Addis Ababa, ETHIOPIA
Ethiopian Airlines Enterprise	P.O.Box 1755 Addis Ababa, ETHIOPIA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

Finland

Airfix Aviation Oy	Tullimiehentie 4-6 01530 Vantaa, FINLAND
Arctic AirService Ky	Lentopaikantie 1 97700 Ranua, FINLAND
Joen Service Oy	Lentoasemantie 30 80140, Joensuu, FINLAND
Konekorhonen Oy	Ilmailutie 74 05820 Hyvinkää, FINLAND
Lapland Technical College Aircraft Maintenance	Kairatie 75 96190 Rovaniemi, FINLAND

France

Aéraudit	Aérodrome Toulouse-Lasbordes 40, rue René Lagasse 31130 Balma, FRANCE
Aéro Carpiquet Sarl	Le Haut Marcelet 14740 Saint Manvieu Norrey, FRANCE
Aéro Club Air France Nord	Aérodrome du Plessis-Belleville 60950 Ermenoville, FRANCE
Aéro Dordogne Services	Aéroport de Bergerac 24100 Bergerac, FRANCE
Aéro Flandre Maintenance	Z.I. du petit pacault Aérodrome 59660 Merville, FRANCE
Aero Service Atlantique EURL	Rue du Jura 17000 La Rochelle, FRANCE
Aéro Services	Aérodrome 2492 Route de Thiberville 27306 Bernay, FRANCE
Aéro Services Mimizan	Aérodrome 40200 Mimizan, FRANCE
Aéroclub Annecy	60, Route de l'Aérodrome 74960 Meythet, FRANCE
Aéroclub d'Orléans et du Loiret (ACOL)	Aérodrome d'Orléans 45550 St. Dennis de l'Hotel, FRANCE

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
12/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Aéroclub de Bordeaux	Aérodrome de Léognan-Saucats 305 Avenue de Mont de Marsan 33850 Leognan, FRANCE
Aeroclub de Champagne	Aerodrome de Reims-Prunay 51360 Prunay, FRANCE
Aéro-Club de L'Herault	Languedoc - Roussillon Aéroport International de Montpellier Méditerranée 34134 Maugio, FRANCE
Aéroclub de la Haute-Saone / AC du Pays de Montbeliard	Aérodrome de Vesoul-Frotey BP 60229 70004 Vesoul Cedex, FRANCE
Aéro-Club du Bassin Minier	BP 16 71300 Montceau les Mines, FRANCE
Aero-Club du Cantal	Airport Aurillac-Tronquieres 15000 Aurillac, FRANCE
Aeroclub du Dauphine Maintenance	Aerodrome 38420 Le Versoud, FRANCE
Aéroclub du Havre Jean Maridor	Aérodrome du Havre-Octéville 76620 Le Havre, FRANCE
Aéroclub Paul Tissandier	Aérodrome de St. Cyr 78210 St. Cyr l'Ecole, FRANCE
Aéroclub Vauclusien	Aérodrome Avignon-Caumont 84140 Montfavet, FRANCE
Aéroclub Vosgien	160, Route de l'Aviation 88000 Dogneville, FRANCE
Aeroglide	Sainte Anne 04700 Puimichel, FRANCE
Aeronav87 Maintenance	Aéroport International 87100 Limoges, FRANCE
Air Intervention Sarl	Aérodrome RN 10 37250 Sorigny, FRANCE
Air Maintenance	Aéroport du Touquet 62520 Le Touquet, FRANCE



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Air Services Caraibes S.A.R.L.	Aéroport du Raizet 97139 Abymes Guadeloupe, French West Indies (FRANCE)
Airways College	Aérodrome Agen La Garenne 47310 Estillac, FRANCE
Alsace Air Maintenance	Aérosport de Colmar 68000 Colmar, FRANCE
ASTONTEC SAS	Aéroport de Toussus le Noble Bat.313 78117 Toussus le Noble, FRANCE
ATA	Aerogare D'Avignon 141, Allee de la Chartreuse 84140 Montfavet, FRANCE
Avialaval sarl	Aérodrome Laval Entrammes 53260 Entrammes, FRANCE
Belledonne Aéro Maintenance	Aérodrome du Versoud 38420 Le Versoud, FRANCE
Blue Aéro SARL	Aéroport de Grenoble St Geoirs 38590 St Etienne de St Geoirs, FRANCE
Bourgogne Aéro Services	Hangar Nord Aérodrome Auxerre Branches 89380 Appoigny, FRANCE
Cassidian Aviation Training Services SAS	Base Aerienne 709 16109 Cognac AIR, FRANCE
C.E.A.P.R. SAS	1 Route de Troyes 21121 Darois, FRANCE
Cholet Aviation	Aérodrome le Pontreau 49300 Cholet, FRANCE
Dinan Aviation SIBA Avionique	Aérodrome de Dinan Trelivan 22100 Dinan, FRANCE
Egide Aviation	Aéroport Chateauroux Deols Rue Georges Clemenceau Bat. 1250 36130 Deols, FRANCE
ENAC	Rue de l'Aviation BP 30080 31603 Muret, FRANCE

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
14/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
ESMA	Aéroport Montpellier Méditerranée CS 1000534137 Manguio Cedex, FRANCE
Fly West Loisirs Sarl	12 Allée Raymond Bazin Aérodrome 85200 Fontenay le Comté, FRANCE
Icarius Aerotechnics	Aéropole 05130 Tallard, FRANCE
Jolliet Electronique	Rue du Pommier 39100 Gevry, FRANCE
Lille Aéro Maintenance SARL	Aéroport de Lille Lesquin Espace Aviation Loisirs 59810 Lesquin, FRANCE
Locat'Air SAS	Aéroport de Roanne LFLO Route de Combray 42155 Saint Léger sur Roanne, FRANCE
Locavia	Aérodrome de Lille-Marcq 59587 Bondues, FRANCE
Marre Aviation	Aérodrome 26200 Montelimar, FRANCE
Nogaro Aviation	Aerodrome 32110 Nogaro, FRANCE
PAM	Hangar H5 Airport Lyon / Bron 69500 Bron, FRANCE
Paris Nord Technique	Aérodrome de Persan-Beaumont 95340 Bernes sur Oise, FRANCE
Pitet Air Service	Route de l'Aviation 88000 Dogneville, FRANCE
Rectimo Aviation s.a.s.	Aéroport Chambéry / Aix les Bains 73420 Viviers du Lac, FRANCE
Riviera Plane Maintenance RPM	54, Aéroport de Cannes Mandelieu, Hangar 7 06150 Cannes La Bocca, FRANCE
Roanne Aéro Maintenance	Aéroport de Roanne Renaison Route de Combray 42155 St Léger Sur Roanne, FRANCE

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
15/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Robin Aircraft	1 Route de Troyes 21121 Darois, FRANCE
Seram – Aeromat	Aérodrome de Villefranche 69620 Frontenas, FRANCE
Strasbourg Air Service	20, Rue St-Exupery 67500 Haguenau, FRANCE
Xenon Aviation	Aerodrome de Vannes 56250 Monterblanc, FRANCE

Germany

Aero Club Coburg e.V.	Brandensteinsebene 96450 Coburg, GERMANY
Aero Technik Klaus Siemers GmbH	Flughafen Geb. 347 Geschäftsfliegerzentrum 22335 Hamburg, GERMANY
Aerodata AG	Hermann-Blenk-Str. 34-36 38108 Braunschweig, GERMANY
Aerowest GmbH	Nordstraße 18 30669 Hannover, GERMANY
AIR LLOYD Aerotechnics GmbH	Flughafen 34379 Calden, GERMANY
AIR LLOYD Aerotechnics GmbH	Flughafen 13 06188 Oppin, GERMANY
Air Service Fiedler	Wilhermsdorfer Straße 33 09387 Jahnsdorf, GERMANY
Air Service Klausheide GmbH	Airportallee 1 48268 Greven, GERMANY
Aircraft-Service Luftfahrttechnik	Flugplatz Mainz Finthen Halle 5a 55126 Mainz, GERMANY
AirPlus Maintenance GmbH	Flughafen 28 88046 Friedrichshafen, GERMANY
ARDEX Aviation Maintenance GmbH	Flugplatz 4 16866 Kyritz, GERMANY
Augsburg Air Service GmbH	Flughafenstraße 5 86169 Augsburg, GERMANY

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
16/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
CD Aircraft Maintenance GmbH	Flugplatz A1 14959 Schönhagen, GERMANY
Diamond Aircraft Industries Deutschland GmbH	Hans-Fleissner-Str. 63329 Egelsbach, GERMANY
DOTEC GmbH	Am Flughafen 26 87766 Memmingerberg, GERMANY
DS-AIR-Service GmbH	Buchenweg 15 26452 Sande, GERMANY
Flugausbildungsverein Erdmannhausen e.V.	Kirchbergerstr. 3 71729 Erdmannhausen, GERMANY
Flugtechnik Stuttgart GmbH	General Aviation Terminal(GAT) 70629 Stuttgart, GERMANY
Flugwerft Aalen GmbH	Hinteres Härdtle 7/1 73450 Neresheim, GERMANY
Flugzeugreparatur Damme GmbH	Am Flugplatz 20 49401 Damme, GERMANY
Flugzeugservice Claassen	Brunshofstr. 5 45470 Mühlheim, GERMANY
Flugzeugservice Petersen	Ochsenweg 203 24941 Flensburg, Germany
Flugzeugtechnik Winkler	Tauschaer Straße 94 09322 Penig, GERMANY
Flugzeugwerft Möller GmbH	Flugplatz Hangelar 53757 Sankt Augustin, GERMANY
FSB Aircraft Maintenance GmbH	Flugplatz B2 14959 Schönhagen, GERMANY
FSG Flugservice GmbH	Flugplatz 61203 Reichelsheim, GERMANY
FWB Flugwerft Biberach GmbH	Flugplatz 6 88447 Warthausen, GERMANY
Gilbert Luftfahrttechnik GmbH & Co KG	City Airport Mannheim Seckenheimer Landstr. 170 68163 Mannheim, GERMANY
Gomolzig Aircraft Service GmbH	Eisenwerkstr. 9 58332 Schwelm, GERMANY



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Hanseatischer Fliegerclub Frankfurt e.V., NL Egelsbach	Flugplatz, Haus 4a 63329 Egelsbach, GERMANY
Hanseatischer Fliegerclub Hamburg e. V.	Weg beim Jäger 193, Gebäude 178 22335 Hamburg, GERMANY
K. Malter Air Service	Am Birkenbrühl / Flugplatz 91074 Herzogenaurach, GERMANY
LTB Sammet GmbH	Flugplatz Heubach 73540 Heubach, GERMANY
Luftfahrt-Service Haiml GmbH	Freiburger Straße 15b 79427 Eschbach Flugplatz, GERMANY
MR Flugtechnik GmbH	Am Flugplatz 19 31137 Hildesheim, GERMANY
Nayak Aircraft Service GmbH & Co.KG	Zum Tower 4 01917 Kamenz, GERMANY
Piloten-Service Robert Rieger GmbH	Flugplatz 2 94474 Vilshofen, GERMANY
Piper + Jet Maintenance AG	Fieseler-Storch-Straße 10 34379 Calden, GERMANY
Porta Air Service GmbH & Co KG	Flughafen 9 32457 Porta Westfalica, GERMANY
Röder Präzision GmbH	Flugplatz Egelsbach 63329 Egelsbach, GERMANY
Scheiling Aircraft Service	Zum Tower 10 01917 Kamenz, GERMANY
Salomo Flugzeugservice GmbH	Flugplatz Zeppelinstr 1 19370 Parchim, GERMANY
Solution Air GmbH	Berliner Allee 11-21 Geb. 360, Flughafen 66482 Zweibrücken, GERMANY
Spessart Air Service GmbH	Am Flugplatz 63762 Großostheim, GERMANY
Westflug Aachen Luftfahrt GmbH & Co. KG	Flugplatz Merzbrück 52146 Würselen, GERMANY
Wilhelm Tank GmbH & Co. Mariensiel KG	Flugplatz Mariensiel 26452 Sande, GERMANY

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
18/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

Greece

Aerodoc - Aviation Services	National Airport DE 68100 Alexandroupoli, GREECE
Aeroservices S.A.	Megara Airport 19100 Megara, GREECE
Airflytech Ike	Heraklion "Nikos Kazantzakis" International Airport 71601 Nea Alikarnassos, GREECE
DEDALUS Aviation Services	Thessaloniki International Airport "Makedonia" 55103 Thessaloniki, GREECE
Egnatia Aviation Ltd.	Kavala International Airport 64200 Chrysoupoli-Kavala, GREECE
G.A. Aviation Services S.A.	8, Efklidi Str. 19400 Koropi – Attica, GREECE

Hungary

Avicraft Ltd.	Bercsenyi u. 45 2700 Cegled, HUNGARY
FLY-Coop KFT.	Rakoczi Utca 3 7530 Kadarkut, HUNGARY
Hungarian Aircraft Technology and Service Ltd.	International Airport Fertöszentmiklos, PO Box 23 9444 Fertöszentmiklos, HUNGARY
Magyar Repülökadémia KFT	Kazinczy Utca 18 7143 Öcsény, HUNGARY
Pannon Air Service KFT	Tököl Airport Repülöter Pf. 32 2316 Tököl, HUNGARY

Iceland

Flugverk ehf	Hangar one Reykjavik airport 101 Reykjavik, ICELAND
--------------	--



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
------	---------

India

Academy of Carver Aviation PVT Ltd	P-50 MIDC Airport, Baramati Pume 413133 Maharashtra, INDIA
Asia Pacific Flight Training Academy Ltd.	GMR HIAL Airport Office International Airport, Hyderabad Hyderabad-50040 Telangana, INDIA
Chimes Aviation Private Limited	Dhana Airstrip PO Dhana, District Sagar 470228 Madhya Pradesh, INDIA
Telangana State Aviation Academy	Old Airport road, Post office New Bowenpally 500011 Hyderabad, Telangana State, INDIA

Indonesia

PT ASI Pudiastuti Aviation	Country Woods TH14 12120 Jakarta, INDONESIA
----------------------------	--

Italy

Aero Club Vercelli	Viale Aeronautica, 46 13100 Vercelli, ITALY
ATS s.r.l.	Via dell'Aeroporto, 44/A 43100 Parma Airport, ITALY
Avio Technologies s.r.l.	Aeroporto Boscomantico 37139 Chievo, Verona, ITALY
Diamond Aero s.r.l.	Aeroporto Roma Urbe Via Salaria 825 00138 Rom, ITALY
Flying Club Sabaudia	Via Litoranea Podere 2082 04016 Sabaudia, ITALY
Glasfaser Italiana s.p.a.	Via delle Ghiaie, 3 24030 Valbrembo, BG, ITALY
Max Aviation s.r.l.	Strada Castiglione 01100 Viterbo, ITALY

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
20/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Name	Address
Officine Aeronautiche Ghidotti Srl	Via dei Grilli 5 41012 Carpi, ITALY
Professione Volare s.r.l.	Via C. Seganti, 103 47121 Forli (FC), ITALY
Turin Flying Institute s.r.l.	Strada San Maurizio, 12 10072 Caselle Torinese, ITALY

Ireland

Aircraft Technical Support Ireland Ltd.	Weston Airport Leixlip, Co Kildare, IRELAND
Shamrock Aviation Services Ltd.	Waterford Airport Waterford, IRELAND

Japan

Alpha Aviation Co., Ltd.	5-21 Mita 3-chome 108-0073 Minato-ku, Tokyo JAPAN
IBEX AVIATION Co., Ltd.	5-21-12 Osawa Mitaka-city 181-0015 Tokyo JAPAN
Japan Motor Glider Club Inc.	879 Daitoku Nabekoshinden, Kawachi-machi, Inashiki-gun 300-1336 Ibaragi-ken
Okayama Air Service Co., Ltd.	673 Urayasuminamimachi, Minami-ku 702-8024 Okayama-city, Okayama JAPAN



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Kenya

Aeronav Maintenance Ltd.	Wilson Airport P.O. Box 74714 00200 Nairobi KENYA
Hawk Aviation Services Ltd.	P.O. Box 43441 City Centre G.P.O 00100 Nairobi KENYA
Superior Aviation Services Ltd	Wilson Airport 00100 Nairobi KENYA

Korea

Sunny Air Inc.	#602, 54 Doryoung-ro 690-802 Jeju City, Jeju-do REPUBLIC OF KOREA
----------------	---

Kyrgyzstan

SKY KG Airlines	1/9 Sums koy Lane 720005 Bishkek KYRGYZSTAN
-----------------	---

Latvia

Sia Baltijas Meridians	34 Araisu St. 1039 Riga, LATVIA
Sia 'Profesionalais Sporta Aviācijas Centrs Rīgas Aeroklubs'	Lienes Street 1-17 1009 Riga, LATVIA

Libya

Air Kufra Iron and Steel Co.	KM 6.4 Gaser Ben Ghesheer road P.O. Box 71191 00218 Tripoli, LIBYA
---------------------------------	--

Lithuania

UAB 'AeroEkspresas'	Vytenio 50 03229 Vilnius, LITHUANIA
---------------------	--



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Madagascar

Aeromarine	Hangar Aeromarine Zone Avion Léger Aéroport International Ivato Antananarivo, MADAGASCAR
------------	---

Malaysia

ADMAL SDN BHD	Redland Hangar & Terminal Complex Sultan Abdul Aziz Shah Airport, Lot 1060 Subang, Selangor MALAYSIA
APFT Engineering Sdn Bhd	Hangar Complex, Sultan Ismail Petra Airport Pengkalan Chepa 16100 Kota Bharu, Kelantan MALAYSIA
CTRM Aviation SDN BHD	Composites Technology City Batu Berendam Airport 75350 Melaka MALAYSIA
PRIMA AIR SDN BHD	Jalan Kuala Muda Padang Matsirat 07100 Langkawi, Kedah Darul Aman MALAYSIA

Malta

Falcon Aviation Engineering	Security Gate 1 Malta Internationale Airport LQA 4000 Luqa, MALTA
Maintenance Centre Malta Ltd.	Hangar 6, Gate 2 Malta International Airport LQA 9023 Luqa, MALTA

Moldova

Flight Control Systems s.r.l. Yury Mitrofansky	Str. Sarmizegetusa 15, of. 302-a, b 2060, mun. Chisinau REPUBLIC OF MOLDOVA
---	---



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Morocco	
MDS Aviation	Aéroport de Rabat-Salé Rabat, MOROCCO
Morocco Aviation Private Academy	MAPA Hangar, Benslimane airport King second Hasan street 13000 Benslimane, MOROCCO

Netherlands	
Aero Service B.V.	Emoeweg 24-26 8218 PC Lelystad, NETHERLANDS
ATN Aircraft Division	7903 BE Hoogeveen Plesmanstraat 10, NETHERLANDS
Aircraft Solutions BVBA	Horsterweg 27 6199 AC Maastricht Airport, NETHERLANDS
Aviation Maintenance Rotterdam	Zaventembaan 1 3045 AR Rotterdam, NETHERLANDS
Aviation Technics B.V.	De Zanden 31-33 7395 Pa Teuge Airport, NETHERLANDS
Cycloon Holland B.V.	Olivier van Nortweg 9 5928 LX Venlo, NETHERLANDS
General Enterprises B.V.	Machlaan 6 9761 TK Eelde, NETHERLANDS
International Aviation Support bv	De Zanden 113 7395 PG Teuge, NETHERLANDS
KN Singles and Twins Aviation Consultants B.V.	Flamingoweg 12 8218 NW Lelystad, NETHERLANDS
Rijnmond Air Services B.V.	Rotterdam Airportplein 54 3045 AP Rotterdam, NETHERLANDS
Transal Aero Services B.V.	Calandweg 2 E 4341 RA Arnemuiden, NETHERLANDS
Vliegwerk Holland B.V.	Zealand Airport Calandwag 50-56 4341 RA Arnemuiden, NETHERLANDS
Wings Over Holland B.V.	Emoeweg 28 8218 PC Vliegveld Lelystad, NETHERLANDS



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

New Zealand

Aeromotive Ltd	Steele Road R.D. 2 Hamilton Airport 2001 Hamilton, NEW ZEALAND
Airwork (NZ) Ltd.	Ardmore Airfield Papakura Auckland, NEW ZEALAND

Nigeria

International Aviation College	Ilorin International Airport P.M.B. 1395 Ilorin, Kwara State NIGERIA
PICOMSS Nigeria	Benin Airport Benin, NIGERIA

Norway

Aeromech A/S	Smaflyhavna 2007 Kjeller, NORWAY
N.a.c. Maintenance AS	Bardufoss Lufhavn 9325 Bardufoss, NORWAY
Tromso Flyklubb	Tromso Airport Postb. 2145 9267 Tromso, NORWAY

Pakistan

Hybrid Technics Private Limited	F-9 Walton Airport 54000 Lahore, Punjab PAKISTAN
---------------------------------	--



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Philippines

Adventure Flight Education and Sports, Inc.	Hangar No. 6, General Aviation Area Mactan Int. Airport 6015 Lapu-Lapu City, Cebu REPUBLIC OF THE PHILIPPINES
Asian Aeronautics Services, Inc.	Manuel A. Roxas Highway Clark Special Economic Zone 2009 Clark Field, Pampanga REPUBLIC OF THE PHILIPPINES
Aviation Hub Asia, Inc.	Hangar 3 C/O Omni Aviation Complex Manuel A. Roxas Highway 2009 Clark Field, Pampanga REPUBLIC OF THE PHILIPPINES
PPI Consulting Inc.	BLDG 8324 Subic Bay International Airport 2200 Subic Bay Freeport Zone, REPUBLIC OF THE PHILIPPINES

Poland

Aero Club Spólka z.o.o.	Obory 100 05-510 Konstancin Jeziorna, POLAND
Technics ATSM	4/1 Batystowa Str. 02835 Warsaw, POLAND

Portugal

Aerotecnica, LDA	Aerodromo Municipal de Cascais-Tires 2785-632 San Domingos de Rana, PORTUGAL
CAE Global Academy Evora S.A.	Aerodrome Municipal de Evora Estrada de Viana, Apartado 33 7002 – 501 Evora, PORTUGAL

Qatar

Qatar Aeronautical College	PO Box 4050 Doha, QATAR
----------------------------	----------------------------



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Republic of Korea

Industry-Academic Cooperation Foundation of Hanseo University	236-49, Gomseom-ro, Nam-myun Taeon-gun 32158 Chungcheongnam-do, REPUBLIC OF KOREA
--	---

Romania

Primul Meridian SRL	Vintila Voda Street, No 50 230000 Slatina, Old County ROMANIA
Regional Air Services S.R.L.	Aerodrom Tuzla 907295 Tuzla, Constanta ROMANIA

Russia

JSC "Ural Works of Civil Aviation"	2 G Bahchivandgy St. Sverdlovsk Region 620025 Ekaterinburg, RUSSIA
LLC „R-Technics“	Big Gruszinskaya Street House 40/1, Office 32 123056 Moscow, RUSSIA
Sky Service LLC	Proezd Stroiteley, 1 140500 Lyhovitsy City, RUSSIA

Saudi Arabia

Wallan Aviation	Thumamah Airport Thumamah National Park 11471 Riyadh, SAUDI ARABIA
-----------------	--

Slovakia

SEAGLE AIR-FTO, s.r.o.	Zahumenska 6672/60 91104 Trencin, SLOVAKIA
------------------------	---

Slovenia

AEROSERVICE D.O.O.	Lancovo 10 E 4240 Radovljica, SLOVENIA ICAO Code: LJBL
--------------------	--



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

South Africa

CitiJet Air Charter (Pty) Ltd.	Hangar No. 35 Lanseria Intl. Airport Lanseria REPUBLIC OF SOUTH AFRICA
Kingfisher Aviation (Pty) Ltd.	19 Drommedaris Str. 7140 Gordons's Bay, REPUBLIC OF SOUTH AFRICA
National Airways Corp. (Pty) Ltd.	Hanger 104 C Gate 15 Lanseria Airport 1748 Lanseria, REPUBLIC OF SOUTH AFRICA
Nevergreen Aircraft Industries	Northern Perimeter Road Safair Complex Kempton Park 1620 Johannesburg, Gauteng REPUBLIC OF SOUTH AFRICA
Plane Maintenance Facility cc	Hangar W5, Gate 5 Lanseria Airport Lanseria REPUBLIC OF SOUTH AFRICA
Wingman Aircraft Maintenance	Hangar 'O' Grand Central Airport New Road Midrand REPUBLIC OF SOUTH AFRICA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Spain	
Aircrafttech S.L.	Apartado 115 Hangar 7 17487 Empuriabrava SPAIN
Centro Aéreo Iber, S.L.	Aeropuerto de Cuatro Vientos Hangar No. 7 28054 Madrid SPAIN
Dédalo Aviacion S.L.	AERODROMO de Requena - Hangar 2 Autovia A3, KM 297 46391 Requena, Valencia SPAIN
Futurhangars SL	Hangar 13b -14b Zona Norte Aeropuerto de Sabadell 08205 Sabadell SPAIN
Malaga Air Maintenance S.L.	C/ Carril de la Cordobesa, 40 29003 Malaga SPAIN
Roeder Ibérica S.L.U.	Aeropuerto de Cuatro Vientos, Carretera del Barrio de la Fortuna 10 28054 Madrid SPAIN
Rosique Clasicos Aircraft SL	46 Cami De L´Aleixar 7-2 43201 Reus-Tarragona SPAIN

Sri Lanka	
Openskies Flight Training (PVT) Ltd.	131/4, Horana Road 12500 Panadura, Western Province, SRI LANKA
Sakurai Aviation Limited	228/1/1 Galle Road Ratmalana, SRI LANKA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Sweden	
Air Service Göteborg	Göteborg City Airport 42373 Säve, SWEDEN
Air Service Göteborg AB	Skogsvägen 61 43538 Mölnlycke, SWEDEN
Aviation Maintenance Engelholm AB	Margretetorpsvägen 445 26291 Ängelholm, SWEDEN
Avico Aviation	Sörviken 135 83498 Brunflo, SWEDEN
Bromma Air Maintenance AB	Hangar 4, Bromma Flygplats 16867 Bromma, SWEDEN
Helicraft Nordflygservice AB	Eskilstuna Airport 63506 Eskilstuna, SWEDEN
IAPS	Uppvindsvögen 20 58274 Lindköping, SWEDEN
LTHF-Aviation	Box 215 24123 Eslöv, SWEDEN
OSM Aviation Airtech AB	Hässlögatan 20 72131 Västerås, SWEDEN
Ost Flyg / Diamond Aircraft Scandinavia	Asvägen 23 39365 Kalmar, SWEDEN
Täby Air Maintenance AB	Örebro Airport 70594 Örebro, SWEDEN
Z Airtech	Byggnad 83 F4 83296 Fösön, SWEDEN



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Switzerland	
Aerogroup SA	Blv des Eplatures 56b 2300 La Chaux-de-Fonds, SWITZERLAND
Airla Aircraft Service GmbH	Flugplatz 11 3368 Bleienbach, SWITZERLAND
Airmatec	Flughafenstrasse 19 Flughafen Bern-Belp 3123 Belp, SWITZERLAND
Farner Air Services Swiss SA	Route des Ronquoz 150 1950 Sion, SWITZERLAND
Fliegerschule Birrfeld AG Technischer Betrieb	Flugplatz Birrfeld 5242 Lupfig, SWITZERLAND
Flight Maintenance MFGZ General Aviation Center	Flughafen Zürich 8058 Zürich – Flughafen, SWITZERLAND
Flight Maintenance MFGZ AG	Ueberlandstrasse 271 8600 Duebendorf, SWITZERLAND
Flying-Ranch Maintenance AG	Flugplatz, Kehrstraße 4 6234 Triengen, SWITZERLAND
Lüthl Bernhard ZSW/Präz. Mechanik	Dornhaldestrasse 51 3627 Heimberg, SWITZERLAND
Mecanair SA	Rte de l'Aerodrome 30 1730 Ecuwillens, SWITZERLAND
Motorfluggruppe Thurgau	Flugplatz 9506 Lommis, TG, SWITZERLAND
Ruag Aerospace	Via Aeroporto 6982 Agno, SWITZERLAND
Seiferle Aviation AG	Alte Landstrasse 57 8700 Küsnacht, SWITZERLAND
Skyparts GmbH	Flugplatz 8915 Hausen am Albis, SWITZERLAND



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Thailand

Asian Aerospace Services Ltd.	25th Flr, Chamnan Phenjati Business Center Bldg, 68 / 209 Rama 9 Rd, Huaykwang 1320 Bangkok THAILAND
Civil Aviation Training Center	1032/355 Phaholyothin Road Jompol 10900 Jatujak, Bangkok THAILAND
Northern Aviation Services Co. Ltd.	Saha Group Industrial Park 304 Moo 1, A Bueng 20230 Sri Racha, Choburi, THAILAND

Tunisia

AFA – Airline Flight Academy Centre Makni	Menzah 9 2092 Tunis, TUNISIA
--	---------------------------------



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Turkey	
AFA – Atlantic Flight Academy	Barbaros Hayrettin Pasa MH. 1992, SK. NO: 14 KAT 3 34522 Esenyurt-Istanbul, TURKEY
Ayjet Anadolu Yildizlari Hava Tasimaciligi Ve Ucus Egitim Hizmetleri A.S.	Ataköy 7-10 Kisim Mahallesi Cobancesme E-5 Yan Yol Cd. No:18/2A Selenium Retro Plaza 34156 Bakirköy, Istanbul, TURKEY
EMAIR Havacilik ve Ticaret A.S.	Arif Nihat Asya Sokak No 43 Oran Cankaya 06450 Ankara, TURKEY
Ondokuz Mayıs Üniversitesi Uzaytem	Ondokuz Mayıs Üniversitesi Rektörlüğü Havacilik ve Uzay Teknolojileri Uygulama ve Arastirma Merkezi Mudurlugu-UZAYTEM Istiklal Mah. Tekel Cad. No:2 Ballica Kampusu 19 Mayıs / Samsun , TURKEY
Top Service A.S.	Ataturk Havalimani E Kapisi 34630 Sefakey / Istanbul, TURKEY
Turkish Airlines Technic Inc. Maintenance Center	Ataturk Airport 34819 Yesilkoy Istanbul, TURKEY

Ukraine	
Challenge Aeroport Ltd.	103, Stolichnoe shosse 03131 Kiev, UKRAINE
International Joint-Stock Aviation Company “Urga”	Dobrovolsky Street 1a 25005 Kirovograd, UKRAINE
LLC Rotor Ukraine	51 Lenina Avenue 54029 Mykolaiv, UKRAINE
Mars RK Ltd.	Volynska Str. 66-A 03286 Kiev, UKRAINE

United Arab Emirates	
Fujairah Aviation Academy	Fujairah International Airport PO Box 777 Fujairah, UNITED ARAB EMIRATES



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

United Kingdom	
ACS Aviation Limited ACS Engineering	Hangar 2-3 Perth Aerodrome PH2 6PL Scone Perth, UNITED KINGDOM
Aeros Engineering Ltd.	Hangar Se 16 Gloucestershire Airport GL51 6SP Cheltenham, Gloucestershire, UNITED KINGDOM
Aerotech Aircraft Maintenance LTD	Airpark, Coventry Airport, Rowley Road, Baginton CV3 4FR Coventry, UNITED KINGDOM
Air Nimbus	The Business Centre Llangarron HR9 6 PG Herefordshire, UNITED KINGDOM
Airspeed Aviation Ltd.	Derby Airfield Hilton Road DE65 6GU Derby, UNITED KINGDOM
Airways Aero Associations Ltd.	Wycombe Air Park SL7 3DP Marlow, UNITED KINGDOM
Apollo Aviation Advisory Ltd.	Concorde House 24 Cecil Pashley Way, Shoreham Airport, Shoreham-by-Sea BN43 5FF West Sussex, UNITED KINGDOM
BCT Aviation Maintenance LTD Cardiff Aviation Engineering	Wings Hangar Cardiff International Airport CF62 3BD Vale of Glamorgan, Wales, UNITED KINGDOM
Bristol Flying Centre	Bristol International Airport BS48 3DP Bristol, UNITED KINGDOM
Channel Island Aero Services Ltd. (Engineering)	Aero Club Hangar States Airport JE3 7BP Jersey, Channel Islands, UNITED KINGDOM
CSE Aviation	Oxford Airport, Kidlington OX5 1RA Oxford, UNITED KINGDOM
DEA Aviation Limited	Gamston Airfield, Retford DN22 7NH Nottinghamshire, UNITED KINGDOM
Deltair Airmotive Ltd.	17 Aston Road Waterlooville PO7 7XG Hants, UNITED KINGDOM

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
34/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

DS Worldwide (Civil) Aviation Ltd.	Hangar 603 Eastern Business Park Bournemouth International Airport Christchurch BH23 6NE, Christchurch, Dorset, UNITED KINGDOM
Dynamic Aircraft Maintenance Ltd.	203 Aviation Park East Bournemouth Airport, Eastern Business Park BH23 6NE Christchurch, Dorset, UNITED KINGDOM
Fast Aviation Ltd.	Hangar 237 Bournemouth International Airport BH23 6NE, Christchurch, Dorset, UNITED KINGDOM
Flight Calibration Services Ltd FCSL Engineering	19 Cecil Pashley Way Shoreham Airport BN43 5FF Shoreham-by-Sea, UNITED KINGDOM
Flight Composites c/o Southern Sailplanes	Membury Airfield RG17 7TJ Hungerford, Berkshire, UNITED KINGDOM
Goodwood Road Racing Co.Ltd Aircraft Engineering Division	Goodwood Aerodrome PO18 0PH Chichester, West Sussex, UNITED KINGDOM
London Elstree Aviation Ltd.	London Elstree Aerodrome WD6 3AR Hertfordshire, UNITED KINGDOM
MCA Aviation Ltd.	Hangar 603, Aviation Park North East Bournemouth International Airport BH23 6NE Dorset, UNITED KINGDOM
Multiflight Ltd.	South Side Aviation Centre Leeds Bradford International Airport LS19 7UG Leeds, UNITED KINGDOM
Namair Light Aircraft Maintenance	Draycot Aerodrome Chiseldon, Swindon SN4 0HX Wiltshire, UNITED KINGDOM
Northumbria Aerospace Limited NAL Engineering Ltd @ PTT Aviation Southside	Newcastle International Airport NE13 8BT Woolsington, UNITED KINGDOM
Patriot Aviation Engineering Limited	Hangar 3a Coventry Airport West Coventry Road CV8 3AZ Baginton Coventry, UNITED KINGDOM



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Ravenair Liverpool Business Aviation Centre	John Lennon Airport L24 5GA Liverpool UNITED KINGDOM
Redhill Air Services Ltd. / Airworks Services Ltd.	Blister Hangar, Crabhill Lane Redhill Aerodrome RH1 5PG Redhill, Surrey, UNITED KINGDOM
RGV Aviation Ltd.	Hangar SE40 Gloucestershire Airport GL51 6SP Cheltenham, UNITED KINGDOM
Shropshire Light Aviation	'A' Hangar Sleap Airfield, Harmer Hill SY4 3HE Shrewsbury, UNITED KINGDOM
Silverstar Maintenance Services Ltd.	Hangar 8 Blackpool International Airport FY4 2QY Blackpool, Lancashire, UNITED KINGDOM
Stapleford Flying Club Ltd.	Stapleford Aerodrome Stapleford Tawney RM4 1SJ Essex, UNITED KINGDOM
Tayside Aviation Ltd.	Dundee Airport Riverside Drive DD2 1UH Dundee, UNITED KINGDOM
White Waltham Airfield Ltd.	Waltham Road Maidenhead SL6 3NJ Berkshire, UNITED KINGDOM



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

USA	
A & M Maintenance Services, Inc.	134 S. Clow Int'l Parkway Suite B 60490 Bolingbrook / Illinois, USA
Absolute Aero Inc. dba Absolute Aero Maintenance	22005 Skywest Dr. 94541 Hayward / California, USA
Advanced Lancaster, LP	530 Airport Rd. 17545 Lititz / Pennsylvania, USA
Aero Experts, LLC	6720 S Plumer Ave 85706 Tucson / Arizona, USA
Aero Restorations, Inc.	4660 Jimmy Doolittle Drive Addison Airport 75001 Addison / Texas, USA
Africair, Inc.	13691 SW 145th Court FL 33186 Miami / Florida, USA
Air Shasta Rotor & Wing Inc.	3770 Flight Ave 96002 Redding / California, USA
Alliant Techsystems Operations LLC	173 American Concourse 76106 Fort Worth / Texas, USA
Alpine Aviation, Inc.	13310 Nevada City Ave 95945 Grass Valley / California, USA
AP Aeronautics Inc.	1900 Joe Crosson Dr. 92020 El Cajon / California, USA
Arapahoe Aero dba Apteryx, Inc.	12760 East Control Tower Road, Box K-1, Centennial Airport 80112 Englewood / Colorado, USA
Arlins Aircraft Service	36 Gallatin Field 59714 Belgrade / Montana, USA
ASI Jet AG, LLC	1710 Butterfield Dr. 55350 Hutchinson / Minnesota, USA
AVFLIGHT	1205 Scottsville Rd 14624 Rochester / New York, USA
Baker Aviation, LLC	200 Texas Way, Suite 102 76106 Fort Worth / Texas, USA
Barbers Point Aviation SVCS	91-1259 Midway Road Building 104, Suite 1 96707 Kapolei / Hawaii, USA

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
37/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Blue Line Technical Services LLC	3149 B Swift Creek Rd. 27577 Smithfield / North Carolina, USA
BMV Air Center	701-2 NE 10th St, 33060 Pompano Beach / Florida, USA
Bohlke International Airways	Rural Route 2 Henry E. Rohlsen Airport 00850 St. Croix / U.S. Virgin Islands, USA
BP Air, Inc.	70 Stacy Haines Rd. 08048 Lumberton / New Jersey, USA
Brunetto Flying Service	13053 N. 69th St. 85254 Scottsdale / Arizona, USA
Central Flying Service, Inc.	1501 Bond Street 72202 Little Rock / Arkansas, USA
CFDI Aero	5088 Sabre Drive 76207 Denton / Texas, USA
Clay Lacy Aviation	8285 Perimeter Road South, 98108 Seattle / Washington, USA
Cochise College	4190 W State HWY 80 85607 Douglas / Arizona, USA
Columbia Air Services – BHB LLC	112 Caruso Dr. 04605 Trenton / Maine, USA
Columbia Air Services, Inc.	175 Tower Ave. 06340 Groton / Connecticut, USA
CopaAir Maintenance Services Inc.	20590 SW Citrus Blvd 34956 Indiantown / Florida, USA
CP Aviation Services	8000 Airport Road, Unit 12 88008 Santa Teresa / New Mexico, USA
Daytona Aircraft Services Inc.	561 Pearl Harbor Drive 32114 Daytona Beach / Florida, USA
dba American Avionics Aviators Choice LLC	7023 Perimeter Rd. So. 98108 Seattle / Washington, USA
Diamond Flight Center of Spanish Fork, L.C.	2050 N. 300W. Hangar 34 84660 Spanish Fork / Utah, USA
Embry-Riddle Aeronautical University Fleet Maintenance Center	600 South Clyde Morris Blvd. 32114 Daytona Beach / Florida, USA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Epic Aviation, Inc.	2022 Aero Circle 32168 New Smyrna Beach / Florida, USA
Executive Air Transport Inc.	103 Sinclair Drive 49441 Muskegon / Michigan, USA
Falcon Aviation Services	5 Falcon Dr. 30269 Peachtree City / Georgia, USA
French Field Aviation, Inc. dba Montrose Aviation, Inc.	1681 6450 Rd. Hangar 3A 81401 Montrose / Colorado, USA
Galvin Flying	7001 Perimeter Rd S 98108 Seattle / Washington, USA
Gibbs Service Center	8906 Aero Drive 92123 San Diego / California, USA
Globe Aero LLC	3131 Flightline Drive Suite 102 33811 Lakeland / Florida, USA
Gorge Aviation Services LLC	45 Airport Way 98617 Dallesport / Washington, USA
Gulf Coast Aviation	New Orleans Lakefront Airport 5701 Walter Beech Rd. 70126 New Orleans / Louisiana, USA
Harris Aviation	2150 W Road 4 1 / 2 N 86323 Chino Valley / Arizona, USA
Hillsboro Aero Academy	3565 NE Cornell Rd 97124 Hillsboro / Oregon, USA
Honey B. LLC dba Corvallis Aero Service	5695 SW Airport Place 97333 Corvallis / Oregon, USA
Horizon Aviation Services, Inc.	2801 Airport Rd. 23323 Chesapeake / Virginia, USA
Infinity Aviation Services	117 Perimeter Road 03063 Nashua / New Hampshire, USA
J.A. Air Center	3N060 Powis Rd. 60185 West Chigago / Illinois, USA
JNW Enterprises LLC d.b.a. Cornerstone Aviation LLC	7001 Perimeter Road South, Suite # 102 98108 Seattle / Washington, USA
Kane Aviation LLC	22 Way Point Dr NW 24012 Roanoke / Virginia, USA
Kansas City Aviation Center, Inc.	15325 S. Pflumm Rd. 66062 Oltahé / Kansas, USA

Ersetzt Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 72 / 05.07.2018
Replaces Service Bulletin No. / Date: TM TAE 000-0003, Revision 72 / July 5, 2018

Page
39/43



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Landmark Aviation	14600 N. Airport Drive 85260 Scottsdale / Arizona, USA
Landmark Aviation	1001 Sycolin Road 20175 Leesburg / Virginia, USA
LeTourneau University	2100 S. Mobberly St. 75602 Longview / Texas, USA
Maine Aviation Sales Inc.	100 Yellow Bird Road 04102 Portland / Maine, USA
Michael VanderWal	3064 Pine Creek Dr 98273 Mount Vernon / Washington, USA
Midwest Aviation Center, LLC	525 Turbine Ave. 63005 Chesterfield / Missouri, USA
Midwest Avtech, Inc.	4241 Ed Urban Dr. 61354 Peru / Illinois, USA
Midwest Corporate Air, Inc.	3100 St. Rt. 47 West 43311 Bellefontaine / Ohio, USA
Midwest Corporate Aviation, Inc Superior Mods, LLC	3512 N. Webb Rd. 67226 Wichita / Kansas, USA
Mohawk Technologies, LLC	2633 Lantana Road Suite 30, Hangar 402 33462 Lantana / Florida, USA
MX Aero Global LLC.	2901 East Spring St. Suite A 90806 Long Beach / California, USA
North American Jet Maintenance LLC	1011 South Wolf Road 60090 Wheeling / Illinois, USA
North Star Aviation	3030 Airport Road 56001 Mankato / Minnesota, USA
Northern Air Inc.	5500 44th St. S.E. 49512 Grand Rapids / Michigan, USA
Pacific Air Craft Inc.	41 Airpark Road 08540 Princeton / New Jersey, USA
PDM Aviation LLC	100 Ballard LN 46135 Greencastle / Indiana, USA
Port City Air Inc.	104 Grafton Drive 03801 Portsmouth / New Hampshire, USA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Premier Aircraft Service, Inc.	5540 NW 23rd Avenue BLDG 14 33309 Fort Lauderdale / Florida, USA
Premier Jet Center	14801 Pioneer Trail 55347 Eden Prairie / Minnesota, USA
Pride Aviation Inc.	2955 Airport Road 29153 Sumter / South Carolina, USA
Propel Aviation Services, LLC	14300 S.W. 129 Street Suite # 101 33186 Miami / Florida, USA
Sabena Airline Training Center, Inc.	5010 E. Falcon Drive 85215 Mesa / Arizona, USA
Sawyer Aviation, LLC	15115 N. Airport Dr. #12 85260 Scottsdale / Arizona, USA
Shoreline Aviation Inc.	93 Old Colony Lane 02050 Marshfield / Massachusetts, USA
Sierra Aero LLC	10356 Truckee Airport Rd Hangar #1 96161 Truckee / California, USA
Sierra Mountain Aviation, Inc.	13308 Nevada City Ave 95945 Grass Valley / California, USA
Southern Sky Aviation LLC	4255 East Lake Boulevard 35217 Birmingham / Alabama, USA
SouthTec Aviation LLC	Rowan County Airport 3670 Airport Loop 28147 Salisbury / North Carolina, USA
Southwest Flight Center	15041 N. Airport Dr. #103 85260 Scottsdale / Arizona, USA
Spartan College of Aeronautics	123 Cessna Drive 74115 Tulsa / Oklahoma, USA
Sterling Aviation	145 John Glenn Drive 94520-5606 Concord / California, USA
Streamline Aviation, LLC	4321 General Aviation Avenue Hangar 1 78719 Austin / Texas, USA
Sun Valley Aviation	1 Lodestar Ave 78550 Harlingen / Texas, USA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Take Flight Alaska	1740 East Fith Avenue 99501 Anchorage / Alaska, USA
Tiffin Aire, Inc.	1778 West U.S. Highway 224 44883 Tiffin / Ohio, USA
US Aviation Group LLC	4850 Spartan Drive 76207 Denton / Texas, USA
US Aviation Training Solutions	365 Golden Knights Blvd. 32780 Titusville / Florida, USA
US Flight Aircraft Maintenance	1 Wallingford Rd. 06810 Danbury / Connecticut, USA
Utah State University	2500 North 900 West 84321 Logan / Utah, USA
Utah Valley State College	1185 Mike Jense Parkway 84601 Provo / Utah, USA
Van Bortel Aircraft, Inc.	4912 South Collins 76018 Arlington / Texas, USA
Van Nuys Flight Center	16700 Roscoe Blvd. 91406 Van Nuys / California, USA
Wayman Aviation, LLC	7501 S. Airport Rd. 33023 Pembroke Pines / Florida, USA
West Coast Aircraft Maintenance, LLC	2881 E. Spring St. 90806 Long Beach / California, USA
West Valley Aircraft Services, LLC	1901 Embarcadero Rd. Ste 100 94303 Palo Alto / California, USA
Winner Aviation Corporation	1453 Youngstown-Kingsville Rd. 44473-9797 Vienna / Ohio, USA

Venezuela

Aviaservice, C.A.	Hangar Aviaservice Aeropuerto de Caracas "Oscar Machado Zuloaga" 1210 Charallave, Estado Miranda VENEZUELA
INAC – National Institute of Civil Aviation of Venezuela	Av. Jose Felix Sosa with Av. Luis Roche Torre Britanica de Seguros 2-8 Floors 1060 Caracas, State of Miranda VENEZUELA



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 (37204) 696-0
Fax: +49 (37204) 696-2912
www.continental.aero
info@continentaldiesel.com

Technische Mitteilung / Service Bulletin

Technische Mitteilung Nr. / Datum: TM TAE 000-0003, Revision 73 / 23.08.2019
Service Bulletin No. / Date TM TAE 000-0003, Revision 73 / August 23, 2019

Zulassung: Die technischen Informationen, die in diesem Dokument enthalten sind, wurden im Rahmen der Befugnisse der EASA- Genehmigung als Entwicklungsbetrieb Nr. EASA.21J.010 genehmigt.
Approval: *The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval no. EASA.21J.010.*